

LOCATION	OBSERATIONS	RECCOMANDATION
709 Cedar Avenue	30" tree with roots against curb	Tree root protection plate to be installed
745 Cedar Avenue	30" Red Maple (F1) is in poor condition	Tree to be removed due to poor condition
704 Cedar Avenue	36" Oak (F1) is in poor condition	Tree to be removed due to poor condition
704 Cedar Avenue	36" tree with roots overhanging the curb and pushing the curb out	Tree root protection plate to be installed
708 Cedar Avenue	36" tree with roots overhanging the curb and pushing the curb out	Tree root protection plate to be installed
712 Cedar Avenue	36" tree with roots overhanging the curb and pushing the curb out	Tree to be removed under separate contract
716 Cedar Avenue	36" tree with roots overhanging the curb and pushing the curb out	Tree to be removed under separate contract
720 Cedar Avenue	36" tree with roots overhanging the curb and pushing the curb out	Tree root protection plate to be installed
740 Cedar Avenue	40" tree with roots overhanging the curb and pushing the curb out	Tree to be removed under separate contract