

LOCATION	OBSERVATION	RECOMMENDATIONS
11 Heritage Road	20" Sugar Maple (F1) is in good condition and overhangs part of the curb and road	Tree to be removed due to construction
101 Heritage Road	48" Pin Oak (F1) is in OK condition but and overhangs part of the curb and road	Tree to be removed due to construction
127 Heritage Road	34" Pin Oak (F1) is in poor condition and overhangs part of the road and sidewalk	Tree to be removed due to poor condition
135 Heritage Road	60" Pin Oak (F1) is in good condition and overhangs part of the curb and road	Tree to be removed due to construction
112 Heritage Road	16" Crab Apple (F2) is in poor condition	Tree to be removed due to poor condition
46 Heritage Road	48" tree with roots overhanging the curb and pushing the curb out	Tree to be removed under separate contract
18 Heritage Road	36" tree with roots overhanging the curb and pushing the curb out	Tree to be removed under separate contract
6 Heritage Road	48" tree with roots overhanging the curb and pushing the curb out	Tree to be removed under separate contract