

LOCATION	OBSERVATIONS	RECOMMENDATION
61 Linden Avenue	30" tree with roots against the curb	Tree root protection plate to be installed
57 Linden Avenue	48" Sugar Maple (F1) is in fair condition but have fungus and roots overhanging the curb	Tree to be removed due to construction
53 Linden Avenue	34" Silver Maple (F1) tree is in poor condition	Tree to be removed due to poor condition
2-10 Linden Avenue	20" American Linden (F2) stalk	Tree to be removed due to construction
32 Linden Avenue	30" Honey Locust (F1) is in good condition with roots overhanging the curb	Tree to be removed due to construction
32 Linden Avenue	30" tree with roots against curb	Tree root protection plate to be installed
36 Linden Avenue	36" Silver Maple (F1) is in good condition slightly pushing curb out	Tree to be removed due to construction
44 Linden Avenue	30" Pin Oak (F1) is in good condition with roots overhanging the curb	Tree to be removed due to construction
44 Linden Avenue	36" tree with roots overhanging the curb and pushing the curb out	Tree to be removed due to construction
54 Linden Avenue	36" tree with roots against curb	Tree root protection plate to be installed
54 Linden Avenue	36" tree with roots against curb	Tree root protection plate to be installed
66 Linden Avenue	48" tree with roots overhanging the curb and pushing the curb out	Tree root protection plate to be installed
66 Linden Avenue	40" tree with roots overhanging the curb and pushing the curb out	Tree root protection plate to be installed
70 Linden Avenue	38" London Plane (F1) is in good condition with roots overhanging the curb	Tree to be removed due to construction
Patco Lot	30" tree with roots overhanging the curb and pushing the curb out	Tree to be removed due to construction
Patco Lot	26" Sweetgum (F6) is in fair condition with roots overhanging the curb	Tree to be removed due to construction
17 Kings Highway West	24" tree with roots against curb	Tree root protection plate to be installed