

LOCATION	OBSERVATIONS	RECOMMENDATION
22 W Summit Avenue	20" Ash (S1) is in poor condition	Tree to be removed due to poor condition
18 W Summit Avenue	30" tree with roots overhanging the curb and pushing the curb out	Tree to be removed due to construction
6 W Summit Avenue	24" Red Oak (F1) is in good condition that slightly pushed the curb out	Tree to be removed due to construction
7 W Summit Avenue	20" Honey Locust (F1) is in poor condition that overhangs the curb and the road	Tree to be removed due to poor condition
17 W Summit Avenue	10" tree in poor condition	Tree to be removed under separate contract
25 W Summit Avenue	20" Ash (S1) is in poor condition	Tree to be removed due to poor condition
401 Washington Avenue	28" Sugar Maple (S1) is in good condition slightly pushing the curb out	Tree to be removed due to construction
645 Washington Avenue	14" Willow Oak (S1) is in good condition and slightly pushes the curb out	Tree root protection plate to be installed