	1001000	
Index No.	4024099	

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER		
NORTH QUARTER Corner of Section 33 , Township 40 , Range 24 , 4TH P.M.		
STATE OF MINNESOTA, County of KANABEC		
At the corner location shown on the sketch: On 05/ /2004 Set a Kanabec County Monument.	Kanabec County U.S. Survey Feet Coordinates NAD 1983, HARN 1996 Adjustment Obtained by RTK GPS Observation Northing= 169083.61	
	Easting= <u>388235.08</u> Note: NAD 1983, HARN 1996 Adjustment coordinates are NOT compatible with NAD 1983 coordinates Note: 1 Meter=3937/1200 U.S. Survey Feet	
SKETCH OF REFERENCE TIES		
GRAVEL ROAD 35.62 30.62 SPIKE IN NORTH FACE POWER POLE SPIKE IN EAST FACE FENCE POST 35.62 CL 230TH AVENUE AVENUE SPIKE IN TOP OF WOOD FENCE POST		
Statement of evidence relative to this corner location is on back of page.		
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. Constant Many 6-07-204 Signature Date	OFFICE OF THE COUNTY RECORDER County of I hereby certify that this document was filed in the County Recorder's office atM. on theday ofA.D., 20	
Registration No. 9808	County Recorder	
Land Surveyor, [] Professional Engineer	BYDeputy	
[] County Surveyor, [] County Engineer	DOCUMENT NO.	

STATEMENT OF EVIDENCE

Original corner was set by Government Surveyor Silas Barnard in October 1855. The wooden post and bearing trees no longer remain.

There is a road order on file at the Kanabec County Assessors Office dated May 22, 1905 which F.B. Vickery surveyed from the Northwest corner of Section 33 to the North Quarter corner.

In April 2004, E.G. Rud ran a survey around Section 28 to tie in lines of occupation and existing monuments.

On May 3rd, we excavated a 10 foot by 13 foot hole 1 foot into the natural ground on the centerline of 230th Avenue and an old fence line to the north. This road bed had been subject to frost and we encountered a lot of pit run rock that had been hauled in. Topsoil was found on south 1/2 of road, but on north 1/2, no sign of topsoil. Any evidence as to the perpetuation of the corner was lost due to road maintenance. We set a #7 rebar 24" long at the fence line extended and on the centerline of the road. This fell 2 feet west of a split between the Northwest and Northeast Corners of Section 28. We took ties and established Kanabec County Coordinates on the monument using G.P.S. equipment.