

CONSTRUCTION OBSERVATION REPORT

Date: November 17, 2021 Time On Site: 3:00 PM Time Off Site: 4:00 PM

Project: Middlebury River Flood Resiliency Project (15032.00002)

Observed By: Roy Schiff

Weather: Clear, 45°F, normal flows

weather: Clear, 45°F, normal now

Equipment / Operator

- CAT 325CL Excavator Markowski Excavation, Inc. (Grist Mill Road floodwall)
- CAT CS-323C Compactor Markowski Excavation, Inc. (Grist Mill Road floodwall)
- CAT Skid Steer Markowski Excavation, Inc. (Grist Mill Road floodwall)

Personnel

• Sam Markowski, Markowski Excavation, Inc.

Construction Activity

• Backfilling behind flood wall.

Design/Construction Notes

- Wall complete, forms removed, Parent Construction demobilized.
- Backfilling gravelly material behind wall. Filling in 1-2 foot lifts and compacting. Not filling along downstream section that was poured last so it will properly cure.
- Some tasks to be completed
 - Seed and mulch behind existing flood wall where repairs took place.
 - o Complete repair of existing flood wall. One small section remains.
 - Complete filling holes in concrete from forms. Lower holes are already filled.
 - Remove concrete "pads" along river used to anchor forms. Also remove trash along based of wall near river before filling.
 - o Plantings.
 - Remove access road.
 - Create ramped fill along back of wall and install topsoil layer for spring plantings.

Compliance Notes

- No discharge of turbid water observed at any sites.
- Time extension to December 1 has been approved by project regulators to allow for the access road to remain in place along the existing and proposed flood wall.

Schedule

Backfilling to continue before and after pending holiday.

Photographs



Figure 1: View of completed flood wall extension from the Grist Mill Road Bridge.



Figure 2: Filling behind wall with gravelly material.



Figure 3: Concrete pads to be removed from site when access road material will be moved to the wall to protect new foundation.