

STATEMENT OF EVIDENCE

From tie sheet 935

This corner was monumented and recorded in 1971 by John Oliver, a Registered Land Surveyor, and removed in reconstruction of County Highway No. 11. A new corner location was filed in 1991.

A search was made and the monument was not found.

A bridge spike above a 5/8" rebar was found, but did not fit the ties from 1991 corner certificate.

This corner was reset from measurements from other monuments in Section 6 from Registered Land Surveyor, John Oliver's notes from 1971.

In August 2004, we ran a survey around Sections 6 and 7 and found this rebar. The one remaining tie fit this rebar. We established Kanabec County Coordinates on this monument using GPS equipment.