CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

North Quarter Corner of Section 34, Township 42 North, Range 23 West, 4th Principal Meridian, Kanabec County, State of Minnesota

At the corner location shown on the sketch: On 5/24/2017 set a 7/8" x 20" Rebar Monument with Aluminum Cap.

Kanabec County U.S. Survey Feet Coordinates NAD 1983, HARN 1996 Adjustment Obtained by RTK GPS observation

Northing: 230146.7994 Easting: 415644.2435

Note: NAD 1983, HARN 1996 Adjustment coordinates are NOT compatible with

NAD 1983 coordinates

Note: 1 Meter = 3937/1200 U.S. Survey Feet


SKETCH OF REFERENCE TIES

KROSCHEL LAND SURVEYORS, INC.
ASSUMES NO LIABILITY FOR THE ACCURACY
OF THE GPS COORDINATES SHOWN HEREON.
ALL COORDINATES AND DIMENSIONS
SHOULD BE FIELD VERIFIED BY THE USER.

NOT TO SCALE

THE BASIS OF BEARINGS FOR THIS DRAWING IS THE KANABEC COUNTY COORDINATE SYSTEM BY MNDOT, NAD 1983, HARN 1996 ADJUSTMENT

SECTION 27



SECTION 34



Kroschel Land Surveyors, Inc.

1639 Main Street North, Suite 6, Pine City, MN 55063 Phone: 320-629-3267 Fax: 320-629-0176

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this survey, plan, or report was prepared by me or under my direct supervision, that the United States public land survey monument record is correct and complete to the best of my knowledge and belief, and that I am a duly Licensed Land Surveyor under the laws of the State of Minnesota.
72-27-20/7 Tyler J. Kroschel Date
License No. 44490
☐ Land Surveyor

OFFICE OF THE COUNTY RECORDERCounty of Kanabec

I hereby certify that this document	was filed in the
County Recorder's office at	M. on the
day of	A.D.,20
County Recorder	
Ву	,Deputy
DOCUMENT NO	

Statement of Evidence:

In October of 1851, Deputy Surveyor John Gay set a post to mark the North Quarter Corner of Section 34, Township 42 North, Range 23 West, 4th Principal Meridian.

Reference ties were taken to:

6 inch Balsam at North 25 degrees West a distance of 24 links 12 inch Balsam at South 18 degrees East a distance of 16 links

All of the original Government corner evidence was searched for. None was found.

1926— A Supervisor's Township Road Order was filed in the Office of the County Auditor opening a town road along the north line of Section 34. No survey information is attached to the Road Order.

In May 2017, a survey was made around Section 27, Township 42 North, Range 23 West, 4th Principal Meridian for Dan Plattner to locate existing monuments, lines of occupation and establish search areas.

On 5/23/2017 we made a 15' x 15' x 3' deep excavation with a Skid Steer at the centerline of the town road and halfway between the Northeast and Northwest corners of Section 34. No evidence of the corner was found in the excavation.

On 5/24/2017 I set a 7/8" x 20" Rebar with Aluminum Cap at the centerline of the township road and halfway between the Northeast and Northwest corners of Section 34. Established reference ties and assigned Kanabec County Coordinates.

This location was determined to be the best available evidence of the original corner location.

