

4124099


Index No. _____

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

North Quarter Corner of Section 33, Township 41, Range 24
4th Principal Meridian, State of Minnesota, County of Kanabec

At the corner location shown on the sketch:

- On 5/18/2010 found a CAPPED IRON PIPE 4.20 WEST AND 0.49 NORTH OF
DATE POSITION
 left monument as found, lowered monument, removed monument (explain)
- On 6/1/2010 Placed a 3/4" X 24" rebar with DNR cap marked 19839 at
DATE
Lost position (Single Proportion)



Kanobec COUNTY
 COORDINATE SYSTEM
 NAD 83 1996 ADJ.
 N = 197378.685
 E = 377531.343

Statement of evidence for this corner location is on back of this page. July 1, 2010
 AMA00321

I certify that this document was researched and prepared by me or under my direct supervision.
 SIGNATURE Paul A. N... DATE 12/7/2010 License Number 19839
 Title: Land Surveyor Professional Engineer County Surveyor County Engineer

Statement of Evidence for the North Quarter Corner of Section 33,
Township 41 North, Range 24 West of the 4th Principal Meridian.
Kanabec County, Minnesota

1855 Deputy Surveyor Banker notes indicate East Random between Section 28 & 33, Va $11^{\circ} 06'$, 80.22 Chains, Int Meridian Sec line 12 links north of post, West corrected between Sections 28 & 33.

Va $11^{\circ} 01'$
At 40.11 chains Set $\frac{1}{4}$ Sec. Post, White Birch 7" N 10° W 32 links, W. Birch 6" S 81° W 63 links.

Neither the monument nor the accessories were found during this survey.

2010 We met with County Surveyor Ernest Rud and he did not have additional records on this particular corner.

We set this corner at the mid-point between and on line between NE & NW corner of Section 33 at the centerline of a road grade in a pasture. We set a $\frac{3}{4}$ " X 24" Rebar with Plastic Cap marked MN DNR 19839.

For more information concerning this survey contact Minnesota DNR.