

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTHEAST Corner of Section 9, Township 42, Range 22, 4TH P.M.

STATE OF MINNESOTA, County of KANABEC


At the corner location shown on the sketch:

On _____ found a _____
DATE

left monument as found, lowered monument, removed monument (explain)

On 9/15/97 Placed a SPIKE REPLACED WITH A 3/4" X 24" IRON ROD WITH A "MNDNR SURVEY
DATE MARKER' CAP

SKETCH OF REFERENCE TIES



KANABEC CO.
COORDINATES

N 250909.35
E 444848.95

NO GOOD TIES AVAILABLE

Statement of evidence relative to this corner location is on back of page.

12/98
WMA00271

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

John D. Walker 12/8/98
SIGNATURE DATE

License Number 16098

Land Surveyor, Professional Engineer
 County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER
County of _____

I hereby certify that this document was filed in the Co. recorders office at _____ M. on the _____ day of _____ A.D., 19____
County Recorder _____
By _____, Deputy
DOCUMENT NO. _____

Northeast Corner Section 9, Township 42 North, Range 22 West

The DNR Bureau of Engineering contacted the following for survey information:

Minnesota Secretary of State's Office
Kanabec County Recorders's Office
Kanabec County Highway Engineer
Kanabec County Surveyor
Bill Hayden, Land Surveyor
Terrence Johnson, Land Surveyor

1855 U.S. General Land Office notes obtained from the Secretary of State's Office states that a post was set to mark the corner with the following bearing trees marked:

W. Pine 14" N 25° E 23 links (15.18 feet)
W. Birch 12" N 69° 15' W 17 links (11.22 feet)
Sugar 10" S 2° 50' W 36 links (23.76 feet)
Sugar 15" S 31° E 30 links (19.80 feet)

1903 County Surveyor, John Nelson, surveyed a road in section 10 from the east quarter corner to the west quarter, thence north to the northwest corner. He measured 40.06 chains from the west quarter corner to the northwest corner.

1997 MN DNR Bureau of Engineering searched for the corner. A spike was set in the center line of the north-south road and in line with a tree line west.

1998 The DNR replaced the spike with a DNR Survey Marker. The spike fits the existing occupation and agrees within 6' of the 1903 distance to the quarter corner.

For more information on our survey in this area please contact MN DNR, Bureau of Engineering, Survey Section, 1601 Minnesota Drive, Brainerd, MN 56425