

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


EAST QUARTER Corner of Section 32, Township 42 N, Range 22 W, 4th P.M.

STATE OF MINNESOTA, County of KANABEC

At the corner location shown on the sketch:

- On 9-20-95 found a FENCE INTERSECTION (E-W-S)
DATE
- left monument as found, lowered monument, removed monument (explain)
- On 10-19-95 Placed a 3/4" x 24" REBAR WITH AN ALUMINUM CAP STAMPED: "DNR SURVEY MARKER"
DATE 0.5' N OF WOOD CORNER FENCE POST.

SKETCH OF REFERENCE TIES



NAD 1983
 KANABEC
 COUNTY
 COORDINATES
 N 227289.47
 E 439565.67

NO TIES AVAILABLE

Statement of evidence relative to this corner location is on back of page.

MARCH 1997
WMA01539

I hereby certify that this document and the data contained herein was prepared by me or under

my direct supervision.
John D. Walker
 SIGNATURE 3/21/97
 DATE

License Number 16098

- Land Surveyor, Professional Engineer
- County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER

County of _____

I hereby certify that this document was filed in
 the Co. recorders office at _____ .M. on the
 ____ day of _____ A.D., 19__

County Recorder _____

By _____, Deputy

DOCUMENT NO. _____

East Quarter Corner Section 32, Township 42 North, Range 22 West, 4th P.M.

The Department of Natural Resources, Bureau of Engineering (BOE) made the following contacts for information concerning this corner:

Minnesota Secretary of States Office
County Auditor, Engineer, Recorder and Surveyor

1855 The U.S. General Land Office set a post to mark this corner and the following bearing trees were marked:

Tamarac 4" S 29° 30' W 44 links (29.04')

Tamarac 5" S 20° 30' W 43 links (28.38')

1995 The BOE searched for the corner in the area of fences east, west and south. Nothing more than the corner fence post was found. Area land owners stated that the fence has always been regarded as the corner. Based on this information the corner was believed to be obliterated. A DNR survey marker was set at the north base of the corner fence post. This corner is 2649.06' from the northeast corner and 2639.12' from the southeast corner of section 32 and 4.4' east of being on a straight line between corners.

For information regarding this survey, contact the MN Department of Natural Resources, Bureau of Engineering, Survey Section, 500 Lafayette Road, St. Paul, MN 55155-4029.