

SW CORNER, SEC. 31, T42, R23

STATEMENT OF EVIDENCE

ALL OF THE ORIGINAL BEARING TREES ARE NOW GONE.

THERE IS NO RESURVEY DATA ON FILE FOR THIS CORNER.

THERE ARE NO DEFINITE LINES OF OCCUPATION IN THIS AREA.

ON FEB. 2, 1983, M.B. RUDE SET THIS CORNER BY DOUBLE PROPORTIONAL MEASUREMENT BETWEEN THE E1/4 CORNER OF SEC. 12, T41, R24 AND THE E1/4 CORNER OF SEC. 24, T42, R24 AND THE N1/4 CORNER OF SEC. 2, T41, R24 AND THE SE CORNER OF SEC. 31, T42, R23.

ON MAY 13, 2010, E.G. RUD AND SONS, INC. FOUND THIS MONUMENT, TOOK NEW TIES AND ESTABLISHED KANABEC COUNTY COORDINATES ON THIS POSITION.