



A HERITAGE OF GOOD LIVING

City of Lathrup Village

27400 Southfield Road
 Lathrup Village, Michigan 48076
 248.557.2600
www.lathrupvillage.org

Sidewalk Replacement Program Marking Key

Sec. 62-122. - Standards generally. The required maintaining of such sidewalks shall be such that the sidewalk is kept in reasonable repair and in condition reasonably safe and fit for travel and in conformity with the other specifications and standards enumerated in this article. In all events, sidewalks having defects over two inches in width, depth, or height are required to be replaced or repaired.

DEFECT CODE	DEFECT	DESCRIPTION
A	Stubber	Two adjacent flags with a vertical separation greater than ¼"
B	Cracked	Broken flag with a single crack or multiple cracks
C	Drainage	A flag that has sunken collecting water over more than 25% of the flag. Driveway flag sunken below height of approach
D	Holes/Pitting	Missing concrete greater than two inches in any direction and/or severe pitting of more than 25% of the flag that causes a bumpy or uneven surface. Deteriorated control joints creating a crevasse greater than 2" in width
E	Scaling	Flaking or peeling away of more than 25% of the surface mortar (a gravel-type surface)
H	Slope	Sloped flag greater than 3" per 5 feet side-slope, or more than 1 inch per foot along the travel path
O	Other	Non-typical situation wherein the inspector identifies a hazard or deterioration in the sidewalk flag. Examples include: <ul style="list-style-type: none"> • Asphalt sidewalk • Width less than 5 feet • Sidewalk previously patched with asphalt or concrete
HS	Horizontal Sawcut	Two adjacent flags with a vertical separation between 3/4" and 1 1/4" will be horizontally sawcut to eliminate the trip hazard
RG	Root Grind	Grinding of tree roots