

## Industrial Storm Water Program Requirement

*All facilities with operations listed below must obtain a Waste Discharge Identification number (WDID), issued by the State Water Resources Control Board (SWRCB), **before the City is permitted to issue a business license.** The WDID number can be obtained on-line through the Board's Stormwater Multiple Application and Report Tracking System (SMARTS) <https://smarts.waterboards.ca.gov/smarts/faces/SwSmartsLogin.xhtml>.*

*Go to OSHA's website (<https://www.osha.gov/pls/imis/sicsearch.html>) for assistance in determining the correct SIC code for your operation.*

SIC CODE	TYPE OF OPERATION
Any SIC from 2011 through 4581	Manufacturing, production or transportation <sup>1</sup>
5015, 5093, 5171	Wholesale trade of used auto parts, scrap and waste material or petroleum
4911, 4952, 4953	Electric services, sewerage services or refuse systems
0272	Horse and other equine farms
Any SIC from 0251 through 0259	Poultry and eggs production
Any SIC from 0211 through 0214	Cattle, hogs, sheep and goats livestock
0241	Dairy farms
Any SIC from 1011 through 1499	Mining

<sup>1</sup> Most transportation facilities within the SIC Code range of 4011 through 4581 are EXEMPTED from the requirement to obtain a WDID number IF there are **NO** vehicle maintenance or equipment cleaning operation on-site. SIC Code range 4221 through 4225 MUST obtain a WDID regardless of the operations conducted.