

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

S.W. Corner of Section 11, Township 40, Range 25, 4TH P.M.

STATE OF MINNESOTA, County of KANABEC


At the corner location shown on the sketch

On 4-30-81 found a CONC. MON. WITH METAL PLATE 8"
Date
BELOW SURFACE

left monument as found, [] lowered monument, [] removed monument (explain)

On 4-30-81 placed a 1/2" x 7" IRON PIPE OVER MON.
Date

SKETCH OF REFERENCE TIES



34 1/2

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

M. B. Eagle 5-27-81
Signature Date

Registration No. 8195

Land Surveyor, [] Professional Engineer

County Surveyor, [] County Engineer

OFFICE OF THE REGISTER OF DEEDS

County of Beltrami

I hereby certify that this document was filed in the Register of Deeds office at 10 M. on the

27 day of August A.D., 1981

Register of Deeds Velma J. Besser

By _____, Deputy

DOCUMENT NO. _____

STATEMENT OF EVIDENCE

The Minnesota Department of Transportation found a 1" iron rod at the intersection of roads north and south and fence line east and west in their survey for the Highway No. 47 before construction of Highway No. 47. They set a concrete monument to replace the 1" iron rod after construction.

On April 13, 1981, I found a spike on the surface and a concrete monument 10" below the surface.

I set a 1/2" by ~~2 1/2~~₇" iron pipe on top of the concrete monument.