

# CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTHEAST Corner of Section 20, Township 39, Range 24, 4TH P.M.

STATE OF MINNESOTA, County of KANABEC

At the corner location shown on the sketch:  
ON 5-25-2010 FOUND 1/2" IRON PIPE

Kanabec County U.S. Survey Feet Coordinates  
NAD 1983, HARN 1996 Adjustment  
Obtained by RTK GPS Observation


Northing= 147931.99

Easting= 385678.46

Note: NAD 1983, HARN 1996 Adjustment  
coordinates are NOT compatible with  
NAD 1983 coordinates

Note: 1 Meter=3937/1200 U.S. Survey Feet

## SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

*Ernest L. Rud*  
Signature

11-27-10  
Date

Registration No. 9808

Land Surveyor,  Professional Engineer

County Surveyor,  County Engineer

## OFFICE OF THE COUNTY RECORDER

County of \_\_\_\_\_

I hereby certify that this document was filed in the County Recorder's office at \_\_\_\_\_ M. on the

\_\_\_\_\_ day of \_\_\_\_\_ A.D., 20\_\_

County Recorder \_\_\_\_\_

BY \_\_\_\_\_ Deputy

DOCUMENT NO. \_\_\_\_\_

NE CORNER, SEC. 20, T39, R24

**STATEMENT OF EVIDENCE**

**ALL OF THE ORIGINAL BEARING TREES ARE GONE.**

**M.B. RUDE SET A CAST ALUMINUM MONUMENT AT FENCE CORNER. (FENCE LINE NORTH AND WEST AND EVIDENCE OF OLD ROAD BED SOUTH)**

**THIS LOCATION WAS TESTED BY MEASUREMENTS TO OCCUPATION LINES 1/2 MILE SOUTH AND TO THE SE CORNER 1 MILE SOUTH. M.B. RUDE CONCLUDED THAT THE FENCE CORNER IS THE BEST AVAILABLE EVIDENCE OF THE ORIGINAL CORNER LOCATION, AND COULD NOT BE TREATED AS A LOST CORNER IN VIEW OF THE EXISTING LINES OF OCCUPATION.**

**ON MAY 25, 2010, E.G. RUD AND SONS, INC. FOUND A 1/2" IRON PIPE AT THIS LOCATION WHICH FIT THE ONE REMAINING TIE AND DALE ANDERSON'S MEASUREMENT TO THE N1/4 CORNER AND E1/4 CORNER OF SEC. 20. KANABEC COUNTY COORDINATES WERE ESTABLISHED ON THIS POSITION.**

01-28-11

8188