Index	No

NORTH QUARTER Corner of Section 96 Township 39 Range 23 4TH P.M.  STATE OF MINNESOTA, County of KANABEC  At the corner location shown on the sketch: IN OCTOBER 2005 SET 1/2" IRON PIPE AND ESTABLISHED C.P.S. COORDINTES ON THE LOCATION.  SKETCH OF REFERENCE TIES FROM TIE SHEET 582  SKETCH OF REFERENCE TIES FROM TIE SHEET 582  SKETCH OF REFERENCE TIES FROM TIE SHEET 582  TIES ARE TO SPIKE IN BLAZE IN NEAR FACE  OF SPRUCE  ROW OF SPRUCE  Statement of evidence relative to this corner location is on back of page.  I hereby certify that this document and the data  OFFICE OF THE COUNTY RECORDER	THE PERSON NAMED IN COLUMN NA	CERTIFICATE OF LOCATION OF GOVERNMENT C
NAD 1983. HARN 1996 Adjustment Obtained by RTK OPS Observation Northing= 163834.27  Easting= 409352.28  Note: NAD 1983, HARN 1996 Adjustment Coordinates are NOT compatible NAD 1983 coordinates note: 1 Meter=3937/1200 U.S. Survers of the Sheet 1882  SKETCH OF REFERENCE TIES FROM TIE SHEET 582  SKETCH OF REFERENCE TIES FROM TIE SHEET 582  TIES ARE TO SPIKE IN BLAZE IN NEAR FACE  OF TWIN ELM  Statement of evidence relative to this corner location is on back of page.  I hereby certify that this document and the data  OFFICE OF THE COUNTY RECORDER		
TIES ARE TO SPIKE IN BLAZE IN NEAR FACE  C/L COUNTY ROAD NO. 70  B" TWIN ELM  ROW OF SPRUCE  Statement of evidence relative to this corner location is on back of page.  I hereby certify that this document and the data  OFFICE OF THE COUNTY RECORDER	ent with	IN OCTOBER 2005 SET 1/2" IRON PIPE AND ESTABLISHED G.P.S. COORDINTES ON THE LOCATION.  Northing= 163834.27  Easting= 409352.26  Note: NAD 1983, HARN 1996  Obtained by RTK GPS (  Northing= 163834.27  Easting= 409352.26  Note: NAD 1983, HARN coordinates are NAD 1983 coordinates are
I hereby certify that this document and the data  OFFICE OF THE COUNTY RECORDER		TIES ARE TO SPIIN NEAR FACE  C/L COUNTY ROAD NO. 70  8" TWIN ELM  ROW OF SPRUCE
Thereby Certify that this about the did the details		Statement of evidence relative to this corner location is on back
County of	filed in on the	contained herein was prepared by me or under my direct supervision.  County of I hereby certify that this do the County Recorder's office day of

## STATEMENT OF EVIDENCE:

ALL OF THE ORIGINAL BEARING TREES ARE NOW GONE.

IN 1887, THOMAS R. VICKERY, A SURVEYOR, SET A 4" OAK POST TO MARK THIS CORNER BY SINGLE PROPORTIONAL MEASUREMENT.

IN JUNE 1981, M.B. RUDE RAN A SURVEY AROUND SECTION 6 AND LOCATED THE EXISTING MONUMENTS AND LINES OF OCCUPATION.

THIS CORNER IS IN AN EAST-WEST ROAD AND AN OLD FENCE LINE SOUTH.

AN EXCAVATION WAS MADE WITH THE COUNTY BACKHOE AT THIS CORNER. THE EXCAVATION WAS 15 FEET SQUARE, 3 FEET DEEP, 1 FOOT INTO NATURAL GROUND. NO EVIDENCE WAS FOUND IN THE EXCAVATION.

A 4" BY 17" CAST IRON MONUMENT WAS SET BY SINGLE PROPORTIONAL MEASUREMENT BETWEEN THE NORTHEAST AND THE NORTHWEST CORNERS OD SECTION 6. THIS LOCATION FITS THE ACCEPTED LINES OF OCCUPATION AT THE QUARTER CORNER AND ALSO AT THE SIXTEENTH CORNERS, A QUARTER MILE EAST AND WEST.

IN OCTOBER 2005 E.G. RUD FOUND THIS MONUMENT AND ESTABLISHED KANABEC COUNTY COORDINATES ON THIS POSITION USING G.P.S. EQUIPMENT.