

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTHEAST

2

41

24

~~SOUTHEAST~~

Corner of Section , Township , Range , 4TH P.M.

STATE OF MINNESOTA, County of KANABEC

At the corner location shown on the sketch:

SET A 1/2" BY 3' IRON PIPE, UP 1± FT.

Kanabec County U.S. Survey Feet Coordinates
NAD 1983, HARN 1996 Adjustment
Obtained by RTK GPS Observation

Northing= 224831.03

Easting= 391562.99

Note: NAD 1983, HARN 1996 Adjustment
coordinates are NOT compatible with
NAD 1983 coordinates

Note: 1 Meter=3937/1200 U.S. Survey Feet

SKETCH OF REFERENCE TIES



ALL SWAMP

(NO TIES AVAILABLE)



Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Ernest J. Rud
Signature

12-21-2011
Date

Registration No. 9808

Land Surveyor, [] Professional Engineer

[] County Surveyor, [] County Engineer

OFFICE OF THE COUNTY RECORDER

County of

I hereby certify that this document was filed in the County Recorder's office at M. on the

 day of A.D., 20

County Recorder

BY Deputy

DOCUMENT NO.

NE CORNER, SEC. 2, T41, R24
SE CORNER, SEC. 35, T42, R24

STATEMENT OF EVIDENCE

THE ORIGINAL CORNER WAS SET ON NOVEMBER 6, 1849 BY U.S. DEPUTY SURVEYOR ISAAC BANKER IN A TAMARACK SWAMP AND 4 BEARING TREES NOTED AS:

- 9" TAMARACK @ 18 LINKS BEARING N72°E
- 9" TAMARACK @ 34 LINKS BEARING N70°W
- 9" TAMARACK @ 9 LINKS BEARING S19°E
- 9" TAMARACK @ 28 LINKS BEARING S75°W

NO VISIBLE EVIDENCE COULD BE FOUND FOR THE ORIGINAL CORNER OR BEARING TREES. THIS SWAMPY AREA HAS WATER IN IT.

NO RECORDS OF ANY SUBSEQUENT SURVEYS COULD BE FOUND AT THE KANABEC COUNTY OFFICES..

A 1/2" BY 42" IRON PIPE WITH AN ALUMINUM WAS SET BY SINGLE PROPORTION BETWEEN THE N1/4 CORNER OF SEC. 2 AND THE NE CORNER OF SEC. 1. ANOTHER 42" PIPE WAS SET AS A GUARD POST WITH DOUBLE LATH ATTACHED. NO TIES WERE AVAILABLE WITHIN 700-800 FEET. KANABEC COUNTY COORDINATES WERE ESTABLISHED ON THIS POSITION.