

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

WEST QUARTER Corner of Section 7, Township 41, Range 24, 4TH P.M.

STATE OF MINNESOTA, County of KANABEC

At the corner location shown on the sketch:
On 04/ /2004 Set a Kanabec County Monument.

Kanabec County U.S. Survey Feet Coordinates
NAD 1983, HARN 1996 Adjustment
Obtained by RTK GPS Observation


Northing= 215887.17

Easting= 364715.68

Note: NAD 1983, HARN 1996 Adjustment
coordinates are NOT compatible with
NAD 1983 coordinates

Note: 1 Meter=3937/1200 U.S. Survey Feet

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Ernest J. Reed
Signature

8-03-2004
Date

Registration No. 9808

Land Surveyor, [] Professional Engineer

[] County Surveyor, [] County Engineer

OFFICE OF THE COUNTY RECORDER

County of _____

I hereby certify that this document was filed in the County Recorder's office at _____ M. on the

_____ day of _____ A.D., 20____

County Recorder _____

BY _____ Deputy

DOCUMENT NO. _____

STATEMENT OF EVIDENCE

The original government corner was set in December 1855, by Government Surveyor Isaac Banker. No evidence of the corner or bearing trees remain.

On page 90 of the section corner tie book at Kanabec County, George Jenks stated that on March 31, 1925 he found a bearing tree and set an iron pipe at the corner.

On the M.H.D. right of way map for T.H. 47, it indicates the state used a line between the Northwest and Southwest corners of Section 7 and on a fence line to the east. This fell 62 feet north of the north end of the bridge over the Knife River.

In April 2004, we ran a survey around Sections 7, 8, 17 and 18 to tie in existing monumentation and lines of occupation. We set this corner at a prorated distance based on M.H.D. stationing between the Northwest and Southwest corners of Section 7. This position fell 62 feet north of the north end of the bridge also.

We accepted this location as the best perpetuated position for this corner. We set a 1/2" iron pipe, took new ties, and established Kanabec County coordinates on this monument.