



Statement of Evidence:

In October of 1851, Deputy Surveyor John M. Gay set a post to mark the Northeast Corner of Section 15, Township 41 North, Range 23 West, 4th Principal Meridian.

Reference ties were taken to:

- 18 inch Balsam at South 35 degrees West a distance of 9 links
- 5 inch Balsam at North 39 degrees West a distance of 11 links

All of the original Government corner evidence was searched for. None was found.

Approx. 1984—Terry Johnson, RLS No. 13115, made a survey in Section 10 and computed a location for the Northeast Corner of Section 15, per survey notes given to the Ernie Rud, RLS No. 9808. The date of the survey is unknown. I contacted Terry Johnson to get a copy of his records and he said he could not find them. No Government Corner Certificate was filed at the County Recorders Office.

2001—Ernie Rud, made a survey in Section 10 and established the East Quarter Corner of Section 10 by retracing Terry Johnsons breakdown for section 10. No Government Corner Certificate was filed at the County Recorders Office.

2010—John Walker, RLS No. 16098, set the Northeast Corner of Section 10. It appears he established it by retracing Terry Johnsons breakdown for section 10. No Government Corner Certificate was filed at the County Recorders Office.

In April 2011, a survey was made around Section 15, Township 41 North, Range 23 West, 4th Principal Meridian for Peoples National Bank of Mora to locate existing monuments, lines of occupation and establish search areas. I also located monuments in Sections 10 & 14 to help establish the Northeast Corner of Section 15.

To establish the Northeast Corner of Section 15, I located the monument set by John Walker at the Northeast Corner of Section 10 and the monument set by Ernie Rud at the East Quarter Corner of Section 10. On the extension of the two found monuments, I computed a location by extending a line south from the East Quarter Corner of Section 10 a distance of 2635.12 to match Terry Johnsons breakdown for section 10. This location fits an east—west barbed wire fence good and it fits a proportional measurement between the North Quarter Corner of Section 15 and the North Quarter Corner of Section 14.

On 4/1/2011, a search was made at my computed location for the Northeast Corner of Section 15 by digging with a shovel and using a metal locator. No evidence of the corner was found in the search. I set a 1/2" x 24" iron pipe with an aluminum cap at my computed location. Established reference ties and assigned Kanabec County Coordinates.

STATEMENT OF CONTROL

Survey Control used in the field.

MN/DOT GEODETIC DATABASE STATION NO. 14177 (NABEC MNDT)  
Horizontal Classification Order B

MN/DOT GEODETIC DATABASE STATION NO. 42426 (34 MN065)  
Horizontal Classification Order C



**Kroschel Land Surveyors, Inc.**

1639 Main Street North, Suite 6, Pine City, MN 55063  
Phone: 320-629-3267 Fax: 320-629-0176