

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

N. 1/4 Corner of Section 30, Township 41, Range 22, 4TH P.M.

STATE OF MINNESOTA, County of KANABEC


At the corner location shown on the sketch

On 5-14-92 found a 1/2" IRON PIPE
Date

left monument as found, [] lowered monument, [] removed monument (explain)

[] On _____ placed a _____
Date

SKETCH OF REFERENCE TIES



Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

[Signature] 7-27-92
Signature Date

Registration No. 8195

Land Surveyor, [] Professional Engineer
[] County Surveyor, [] County Engineer

OFFICE OF THE REGISTER OF DEEDS

County of _____
I hereby certify that this document was filed in the Register of Deeds office at _____ M. on the _____ day of _____ A.D., 19_____

Register of Deeds _____
By _____, Deputy

DOCUMENT NO. _____

STATEMENT OF EVIDENCE

All of the original bearing trees are now gone.

This corner falls in an east-west road and a low area near a culvert south. All evidence of this corner would have been destroyed in road construction and replacement of the culvert.

There are two plats on file west of this corner along Pomroy Lake.

In September of 1974, I set a 1/2" iron pipe at this corner from the found monument in the plat of POMROY BEACH. On May 14, 1992, I found the 1/2" iron pipe from my records of 1974.

This location fits a fence line north and south of this corner and the center line of the existing east-west road. This location was accepted as the perpetuated original corner location.