

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

NORTHWEST Corner of Section 31, Township 38, Range 25, 4TH P.M.
STATE OF MINNESOTA, County of KANABEC

At the corner location shown on the sketch:
FOUND A KANABEC COUNTY CAST ALUMINUM MONUMENT WITH
MAGNETS

Kanabec County U.S. Survey Feet Coordinates
NAD 1983, HARN 1996 Adjustment
Obtained by RTK GPS Observation

Northing= 107476.32

Easting= 343268.34

Note: NAD 1983, HARN 1996 Adjustment
coordinates are NOT compatible with
NAD 1983 coordinates
Note: 1 Meter=3937/1200 U.S. Survey Feet

SKETCH OF REFERENCE TIES

from tie sheet 389



SPIKE IN BLAZE
IN 24" PINE
6 FEET UP

88.22



46.40

SPIKE IN
POWER POLE

90.15

SPIKE IN BLAZE
IN 14" ELM

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data
contained herein was prepared by me or under
my direct supervision.

Ernst G. Ruf
Signature

9-30-2008
Date

Registration No. Minn No 9808

Land Surveyor, Professional Engineer

County Surveyor, County Engineer

OFFICE OF THE COUNTY RECORDER

County of _____

I hereby certify that this document was filed in
the County Recorder's office at _____ M. on the

_____ day of _____ A.D., 20 _____

County Recorder _____

BY _____ Deputy

DOCUMENT NO. _____

NORTHWEST CORNER SECTION 31, TOWNSHIP 38, RANGE 25

STATEMENT OF EVIDENCE

NARRATIVE FROM TIE SHEET #389

MONUMENT WAS SET FROM SURVEY OF COUNTY ROAD #4, M.B. RUDE MADE THE SURVEY AND SAID THAT THE MILLE LACS COUNTY HIGHWAY DEPARTMENT IRON PIN WAS GOOD FOR THE SECTION CORNER. RUDE THEN SET A KANABEC COUNTY CAST ALUMINUM MONUMENT WITH MAGNETS IN PLACE OF THE COUNTY'S PIN.

IN MARCH 2008 E.G. RUD & SONS, INC. FOUND THIS MONUMENT AND KANABEC COUNTY COORDINATES WERE ESTABLISHED ON THIS POSITION USING GLOBAL POSITIONING SYSTEM (G.P.S.) EQUIPMENT.