# 2020 School Security Improvement Project

The June 9, 2020 proposition addresses capital improvements at all 13 of the District's schools. The 2020 School Security Improvement Project creates a secured entrance where visitors will have contact with a school administrator before being allowed to enter the school. It also allows for the installation for an immediate school lockdown system, which is similar to a fire alarm system, and includes the installation of a security (shatter proof) film on windows that were identified during the two security reviews conducted by the District at each school. In addition to these security improvements, roofs will be replaced at Williamsville North High School, Country Parkway Elementary School, Forest Elementary School, and Maple East Elementary School.

# PROJECT SCOPE BY BUILDING

# Casey Middle School (built in 1970)

- Secured Entry Main Entrance
- Emergency Lockdown System
- Security film at Entrances
- Security film at Cafeteria
- Main Entry Security Bollards
- Door Hardware All Classrooms
- Security Camera Enhancements
- Visitor Access/Monitoring System
- · Add Emergency Circuits to Bathrooms

### Country Parkway (built in 1968)

- Secured Entry Main Entrance
- · Main Office Renovations Required for Secured Entry
- Emergency Lockdown System
- Security Film at Entrances
- Main Entry Security Bollards
- Door Hardware All Classrooms
- Visitor Access/Monitoring System
- · Add Emergency Circuits to Bathrooms

# Dodge Elementary (built in 1953)

- Secured Entry Main Entrance
- Main Office Renovations Required for Secured Entry
- Main Entry Security Bollards
- Security Film at Entrances
- Security Film at Cafeteria
- Emergency Lockdown System
- Door Hardware All Classrooms
- Add Emergency Circuits to Bathrooms
- Security Camera Enhancements

6

Visitor Access/Monitoring System

Connection BUDGET 2020

## Forest Elementary (built in 1955)

- Secured Entry Main Entrance
- Main Office Renovations Required for Secured Entry
- Main Entry Security Bollards
- Security Film at Entrances
- Security Film at Cafeteria
- Emergency Lockdown System
- Door Hardware All Classrooms
- Security Camera Enhancements
- Visitor Access/Monitoring System
- Conference Room Renovation
- Add Emergency Circuits to Toilet Rooms

#### East High School (built in 1975)

- Secured Entry Main Entrance
- Main Entry Security Bollards
- Security Film at All Entrances
- Secured Vestibule Performing Arts Entrance
- Emergency Lockdown System
- Security Camera Enhancements
- Visitor Access/Monitoring System
- Emergency Circuits to Bathrooms

#### Heim Elementary (built in 1966)

- Secured Entry Main Entrance
- Main Office Reconfiguration Required for Secured Entry
- Main Entry Security Bollards
- Security Film at Entrances
- Emergency Lockdown System
- Doors Hardware All Classrooms
- Security Camera Enhancements
- Visitor Access/Monitoring System
- · Add Emergency Circuits to Bathrooms

### Heim Middle School (built in 1964)

- Secured Entry Main Entrance
- Main Office Relocation and Secure Entrance
  Vestibule Required for Secured Entry
- Main Entry Security Bollards
- Security Film at Entrances
- Security Film at Cafeteria
- Relocate Classrooms
- Security Camera Enhancements
- Visitor Access/Monitoring System
- Provide New PA System
- · Add Emergency Circuits to Bathrooms

#### Maple East Elementary (built in 1959)

- Secured Entry Main Entrance
- Main Office Renovation Required for Secured Entry
- Main Entry Security Bollards
- Security Film at Entrances
- Security Film at Cafeteria
- Emergency Lockdown System
- Door Hardware All Classrooms
- Security Camera Enhancements
- Visitor Access/Monitoring System
- Add Emergency Circuits to Bathrooms
- Conference and Storage Renovation

# Maple West Elementary (built in 1966)

- Secured Entry Main Entrance
- Main Office Renovations Required for Secured Entry
- Main Entry Security Bollards
- Security Film at Entrances
- Emergency Lockdown System
- Door Hardware All Classrooms
- Security Camera Enhancements
- Visitor Access/Monitoring System
- Add Emergency Circuits to Bathrooms

## Mill Middle School (built in 1959)

· Main Office Renovation Required for Secured Entry

• Secured Entry – Main Entrance

· Main Entry Security Bollards

· Security Film at All Entrances

· Emergency Lockdown System

• Door Hardware - All Classrooms

· Emergency Circuits in Bathrooms

Visitor Access/Monitoring System

• Secured Entry - Main Entrance

• Main Entry Security Bollards

• Security Film at All Entrances

· Emergency Lockdown System

• Door Hardware - All Classrooms

Security Camera Enhancements

Visitor Access/Monitoring System

· Renovation of Existing Main Office

· Emergency Circuits in Bathrooms

• Secured Entry - Main Entrance

· Main Entry Security Bollards

· Security Film at All Entrances

· Emergency Lockdown System

• Door Hardware - All Classrooms

• Security Camera Enhancements

Visitor Access/Monitoring System

· Emergency Circuits in Bathrooms

• Secured Entry – Main Entrance

· Main Entry Security Bollards

• Emergency Lockdown System

• Security Film at All Entrances

Security Camera Enhancements

Visitor Access/Monitoring System

· Emergency Circuits in Bathrooms

• Security Film at Cafeteria

• Main Entrance Canopy

www.williamsvillek12.org

• Door Hardware - All Classrooms

· Secured Vestibule

Transit Middle School (built in 1993)

· Security Film at Cafeteria

· Secured Vestibule

South High School (built in 1949)

· Main Office Renovation Required for Secured Entry

· Secured Vestibule

North High School (built in 1968)

· Main Office Renovation Required for Secured Entry

· Security Film at Cafeteria

· Secured Vestibule