Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb				NOTE: Fixture replacement is being prioritized by our facility staff and is occuring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.				
Casey middle			·					1
Location	Room 114 Sink	Room 129 Sink	Room 132 Sink # 2	Room 132 Sink # 5	Stage Sink	Room 139 Sink # 1	Faculty Bathroom Sink # 1	Mezzaninne Sink
Test results	22.2	20.5	15.6	17.8	96.8	21.3	3 37.8	65.6
Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	g Flushing	Flushing
Test results	20.00	20.80	13.10	18.00	29.00	24.4	1 7.42	34.80
Back in use			9/29/2021	[]			9/29/2021	·────────────────────────────────────
Location			ļ					[]
Test results			1	1]'
Remediation			1	· · · · · · · · · · · · · · · · · · ·				'
Results				'				·/
Back in use								· · · · · · · · · · · · · · · · · · ·
Location				ļļ				[]
Test results				,			ļţ	[] '
Remediation			·;	,			1	
Back in use								ļ]
Location			J	ļļ			ļļ	·
Test results				+			++	[]
Remediation				1			+	· · · · · · · · · · · · · · · · · · ·
Back in use			i					
			!					