Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occuring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Country Parkway								
Location	101 Classroom Sink # 1	102 Classroom Sink #1	107 Classroom Sink	108 Classroom Sink	110 Classroom Sink	Speech Office Sink	116 Classroom Sink	117 Classroom Sink
Results	18.10	25.60	18.20	19.40	25.00	19.60	16.00	29.00
Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing
Results	4.12	5.51	6.26	7.89	4.6	8.57	18.4	35.8
Results								
Results								
Back in use	9/29/2021	9/29/2021	9/29/2021	9/29/2021	9/29/2021	9/29/2021		·
								1
Location	121 Classroom Sink	123 Classroom Sink	122 Classroom Sink	124 Classroom Sink	125 Classroom Sink	127 Classroom Sink	12 Kitchen Bathrroom Sink	1
Results	19.70	18.90	24.60	15.60	20.00	15.50	35.90	1
Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	
Results	12.4	9.01	13.8	12.7	23.2	14.8	20.4	
Back in use	9/29/2021	9/29/2021	9/29/2021	9/29/2021		9/29/2021		1
					,			1
Back in use		,	1	,		1		1