## Williamsville CSD

Back in use

Locations of Water Test Samples Greater than 15 ppb				NOTE: Fixture replacement is being prioritized by our facility staff and is occuring in an expedited				
				manner. New water samples are sent to the testing lab with an accelerated turn-around time.				
<u>Forest</u>								
Location	38 Bathroom Sink # 1	36 Classroom Sink	20 Classroom Sink # 3	19 Classroom Sink	12 Classroom Sink	9 Bathroom Sink	1 Classroom Sink	Library Offcie Sink
Test results	98.10	16.80	20.50	15.10	21.60	15.60	138.00	140.00
Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing
Results	29.80	22.10	3.66	16.70	20.80	18.10	2.42	6.85
Back in use			9/29/2021				9/29/2021	9/29/2021
Location								
Test results								
Remediation								
Results								