## **Locations of Water Test Samples Greater than 15 ppb**

NOTE: Fixture replacement is being prioritized by our facility staff and is occuring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

<u>Heim middle</u>								
Location	Room D6 Sink # 1	Boys Locker Room Sink # 1	Room C-13 Eye Wash	Room C-11 Eyewash	Room A-11 Eyewash	omens Lav by Aud Sink # 2	tlet by Steamer in Kitchen	Boiler Room Eye Wash
Test results	28.8	16.7	51.7	93.9	232	19	119	46.9
Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing
Test results	48.9	5.3	4.29	3.84	11.1	8.45	69.2	29.7
Back in svc.		9/29/2021	9/29/2021	9/29/2021	9/29/2021	9/29/2021		
Location								
Test results								
Remediation								
Back in svc.								
Π								
Location								
Test results								
Remediation								
Results								
Back in svc.								
Location								
Test results								
Remediation								
Results								
Back in svc.								
Location								
Test results								
Remediation								
Back in svc.								
Location								
Test results								
Remediation								
Back in svc.								
<b>  </b>								