Wil	liamsvil	lle CSD
-----	----------	---------

•		NOTE: Fixture replacement is being prioritized by our facility staff and is occuring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.						
<u>Heim</u>								
Location	Room 142 Sink	Room 146 Sink						
Test results	16.60	16.80						
Remediation	Flushing	Flushing						
Results	12.90	43.30						
Results 2								
Back in use	9/29/2021							
Location								
Test results								
Remediation								
Results								
Results								
Results								
Back in use								