Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occuring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Test results So.3 202 36.4 36.2 4.0.2 56.8 2.2.3 4.4	<u>Mill middle</u>								
Remediation Flushing Flushi	Location	Principals Offcie Lav Sink	Storage Room by AP Sink	Clinic Bathroom Sink	Room A-1 Sink	Room A-6 Sink	Room A-8 Sink	irls Lav by Room A-11 Sink	Room A-11 Sink
Test results 6.03 1.128 176 43.3 99.7 56.7 6.17 59 Back in svc. 9/39/2021 9/	Test results	30.3	202	26.4	36.2	40.2	56.8	22.3	48.4
Back in svc. 9/29/2021 9		Flushing	Flushing	Flushing	Flushing		, and the second	Flushing	Flushing
Room A-10 Sink		6.03	12.8	176	43.3	39.7	56.7	6.17	50.6
Test results	Back in svc.	9/29/2021	9/29/2021					9/29/2021	
Test results									
Remediation Flushing	Location	Room A-10 Sink	Room A-13 Sink	apped Lav by Library Sink	Room B-6 Sink	torage Room by AP Sink # 2	Boys Lav by A-11 Sink #1	allway Fountain by A-11 #1	Girls Lav by A-11 Sink # 1
Test results		46.2	27.9	26.1		28		42.3	19.5
Back in svc.	Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing
Location m A-11 Classroom Sink # 2 m A-11 Classroom Sink # 3 m A-11 Classroom Sink # 2 m A-11 Classroom Sink # 3 m A-12 m A-12 m A-12 m A-12 m A-13 m	Test results	49.3	29	28.9	30.2	12.8	8.53	ND	4.41
Test results 36.8 53 63.9 41.4 56.4 19.1 17.8 11. Remediation Flushing Flu	Back in svc.					9/29/2021	9/29/2021	9/29/2021	9/29/2021
Test results 36.8 53 63.9 41.4 56.4 19.1 17.8 11. Remediation Flushing Flu									
Remediation Flushing Flushi	Location	m A-11 Classroom Sink # 2	m A-11 Classroom Sink # 2	Room C-11 Sink	Room C-10 Sink	Room C-13 Sink	Room E-3 Storage Sink	Room E-5 Sink # 3	Room E-2 Sink # 1
Test results	Test results	36.8	53	63.9	41.4	56.4	19.1	17.8	19.3
Back in svc. Room E-2 Sink # 2 Room E-2 Sink # 3 Room E-2 Sink # 4 Room E-4 Sink Room E-7 Sink # 1 Room E-7 Sink # 2 Boys Locker Room Sink Girls Locker Room Sink Girls Locker Room Sink Girls Locker Room Sink Room E-7 Sink # 2 Boys Locker Room Sink Girls Locker Room Sink Girls Locker Room Sink Girls Locker Room Sink Room E-7 Sink # 2 Boys Locker Room Sink Girls Locker Room Sink Girls Locker Room Sink Girls Locker Room Sink Room E-7 Sink # 2 Boys Locker Room Sink Girls Locker Room Sink Girls Locker Room Sink Girls Locker Room Sink Girls Locker Room Sink Flushing Flushin		Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing
Location Room E-2 Sink # 2 Room E-2 Sink # 3 Room E-2 Sink # 4 Room E-4 Sink Room E-7 Sink # 1 Room E-7 Sink # 2 Boys Locker Room Sink Girls Locker Room	Test results	48.3	48.3	44.8	29	49	22.4	8.33	16.5
Test results	Back in svc.							9/29/2021	
Test results									
Remediation Flushing	Location	Room E-2 Sink # 2	Room E-2 Sink # 3	Room E-2 Sink # 4	Room E-4 Sink	Room E-7 Sink # 1	Room E-7 Sink # 2	Boys Locker Room Sink	Girls Locker Room Sink # 2
Test results 15.4 29.2 13.5 18.1 29.3 14.2 18.4 22. Back in svc.	Test results	53.5	20	34.3	17.9	45.9	19.4	16.1	40.5
Back in svc. 9/29/2021 9/29/2021 9/29/2021 Location Girls Locker Room Sink # 3 Pasement Storage Sink # 1 9/29/2021 9/29/2021 Test results 15.7 15.7 9/29/2021 Remediation Flushing Flushing Flushing Test results 25.1 9.55 9/29/2021 Back in svc. 9/29/2021 9/29/2021 9/29/2021 Location 10.000 10.000 10.000 10.000 Test results 10.000 10.000 10.000 10.000 10.000 Remediation 10.000 1	Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing
Location Girls Locker Room Sink # 3 Basement Storage Sink # 1	Test results	15.4	29.2	13.5	18.1	29.3	14.2	18.4	21.7
Test results 15.7 15.7 ————————————————————————————————————	Back in svc.			9/29/2021			9/29/2021		
Test results 15.7 15.7 ————————————————————————————————————									
Remediation Flushing	Location	Girls Locker Room Sink # 3	Basement Storage Sink # 1						
Test results 25.1 9.55 9/29/2021 Back in svc. 9/29/2021<	Test results	15.7	15.7						
Back in svc. 9/29/2021 9/29/2021 Location 1 9/29/2021 9/29/2021 Location 1 9/29/2021 9/	Remediation	Flushing	Flushing						
Location Test results Remediation Image: Control of the control	Test results	25.1	9.55						
Test results Remediation	Back in svc.		9/29/2021						
Test results Remediation									
Remediation	Location								
	Test results								
	Remediation								
Back in svc.	Back in svc.								