Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occuring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

					,			
South high								
Location	Room 134 Sink # 1	Room 134 Sink # 2	Room E-6 Sink	om 129 P Dark Room Sink	Room 129 D Sink # 1	Room 129 D Sink # 2	Room 129 D Sink # 3	Room 129 D Sink # 4
Test results	23.5	31.3	18.6	15.8	59.4	16.1	16.8	34
Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing
Test results	57.4	5.69	5.46	15.1	61.2	14.8	20.7	134
Back in use		9/29/2021	9/29/2021			9/29/2021		
Location	v Coaches Girls Off Shower							
Test results	193							
Remediation	Shower, non-potable							
Test results	8/30/2021							
Back in use								
11								
Location								
Test results								
Remediation								
Back in use								
Location								
Test results								
Remediation								
Back in use								
Location								
Test results								
Remediation								
Back in use								
Location								
Test results								
Remediation								
Back in use								
Location								
Test results								
Remediation								
Back in use								
II	•							•