Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occuring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

				manner. New water sum	pies are sent to the testi	ig lab with an accelerate	a tarri aroana time.	
East high								
Location	Pool Room Eye Wash	Kitchen Sink # 5	Kitchen Sink # 8	Room 102 Sink #1	Room 103 Sink # 4	Kiln Room Sink	Room 117 Sink # 4	Room 117 Sink # 6
Test results	2080	20.2	27.5	18.6	20.4	30.4	52.6	97.2
Remediation								
Back in svc.								
Location	Room 117 Sink #7	Room 117 Sink # 8	Room 119 Sink # 1	Room 119 Sink # 2	Room 119 Sink # 3	Room 119 Sink # 4	Room 119 Sink # 5	Room 113 Sink
Test results	101	44.9	32.6	23	71.2	50.4	15.4	38.3
Remediation								
Back in svc.								
Location	Mens Lav by Aud Sink	Health Office Sink # 1	Coaches Office Lav Sink	ys Red locker Room Sink	Kiln Room Sink # 2			
Test results	29.2	21.8	21.2	19.2	30.4			
Remediation								
Back in svc.								
Location								
Test results								
Remediation								
Back in svc.								
Location								
Test results								
Remediation								
Test results								
Back in svc.								
Location								
Test results								
Test results								
Test results								
Remediation								
Back in svc.								