Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occuring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

		mainter. New water samples are sent to the testing lab with an accelerated tarn-around time.							
Mill middle									
Location		Storage Room by AP Sink	Clinic Bathroom Sink	Room A-1 Sink		Room A-8 Sink	Lav by Room A-11 Sink		
Test results	30.3	202	26.4	36.2	40.2	56.8	22.3	48.4	
Remediation									
Back in svc.									
Location	Room A-10 Sink	Poom A 12 Sink	apped Lav by Library Sink	Poom P 6 Sink	age Room by AP Sink # 2	ove Lay by A 11 Sink #1	ray Fountain by A 11 #1	de Lay by A 11 Sink # 1	
Test results	46.2		26.1	18.1			·	19.5	
Remediation	40.2	27.9	20.1	10.1	20	49.2	42.3	19.5	
Back in svc.									
Location	m A-11 Classroom Sink # 2		Room C-11 Sink	Room C-10 Sink		Room E-3 Storage Sink		Room E-2 Sink # 1	
Test results	36.8	53	63.9	41.4	56.4	19.1	17.8	19.3	
Remediation									
Test results									
Back in svc.									
Location	Room E-2 Sink # 2	Room E-2 Sink # 3	Room E-2 Sink # 4	Room E-4 Sink	Room E-7 Sink # 1	Room E-7 Sink # 2	Boys Locker Room Sink	Locker Room Sink # 2	
Test results	53.5	20	34.3	17.9	45.9		•	40.5	
Remediation									
Test results									
Test results									
Back in svc.									
Location	Girls Locker Room Sink # 3	Jasement Storage Sink # 1							
Test results	15.7								
Remediation	15.7	15.7							
Back in svc.									
Location									
Location									
Test results									
Remediation									
Back in svc.									