Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occuring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

		mainter recording to the testing to							
North high									
Location	Boiler Room Source	Conference Room Sink # 1	itchen Dish room Sink #2	iens Lav by C-108 Sink # 3	Room C-108 Sink # 1	Room C-108 Sink # 2	Room C-105 Sink # 1	Room C-152 Sink # 1	
Test results	23.5	21.3	21.9	21.4	24.6	17.1	53.6	19.2	
Remediation									
Results									
Back in use									
Location	Room C-162 Sink # 2	lens Lav by C-130 Sink # 1	ens Lav by C-130 Sink # 2	lens Lav by C-130 Sink # 3	loor Coaches Office Sink	Pump Room Eye Wash			
Test results	92.2								
Remediation									
Test results									
Back in use									
Location									
Test results									
Remediation									
Back in use									
Location									
Test results									
Remediation									
Results									
Back in use									
Location									
Test results									
Remediation									
Back in use									