

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Country Parkway

Location	Rm 119, fountain	Rm 121, fountain	Rm 125, fountain	Staff kitchen lav	IMC, hose bib	Custodial closet #2	Outdoor -Boiler rm	Outdoor-by 122
Results	16.70	17.30	20.20	27.30	13400.00	39.00	131.00	232.00
Remediation	Replaced fountain	Replaced fountain	Replaced fountain	New faucet	Signage	Signage	Signage	Signage
Results	Pending	13.2	Pending	Pending	NA	NA	NA	NA
Back in use		11/1/2016			12/6/16	10/24/16	12/6/16	12/6/16
Location	Outdoor-by115	Outdoor-by108	Outdoor-by 105	Outdoor-by100	Outdoor-by-Office	Girls LR shower	Boys-LR shower	Custodial by rm 100
Results	59.10	135.00	223.00	139.00	198.00	53.90	16.70	27.20
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Results	NA	NA	NA	NA	NA	NA	NA	NA
Back in use	12/6/16	12/6/16	12/6/16	12/6/16	12/6/16	12/6/16	12/6/16	12/6/16
Location	Library office sink	Rm 104, sink	Rm 104, fountain	Rm 106, sink	Rm 106, fountain	Rm 107, sink	Rm 108, sink	Rm 110, sink
Results	17.00	39.30	457.00	20.30	17.60	21.10	26.30	15.90
Remediation	New faucet	New faucet	New fountain	New faucet	New faucet	New faucet	New faucet	New faucet
Results	Pending	Pending	Pending	Pending	Pending	Pending	Pending	Pending
Back in use								
Location	Rm 117, sink	Rm 117, fountain	Rm 118, sink	Rm 118, fountain	Speech office sink	Outdoor-by-120	Outdoor-by-106	
Results	18.10	23.70	22.10	27.00	18.30	77.30	30.20	
Remediation	New faucet	New fountain	New faucet	New fountain	New faucet	Signage	Signage	
Results	Pending	Pending	Pending	Pending	Pending	NA	NA	
Back in use						12/6/16	12/6/16	

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Dodge									
Location	Rm 106, bathroom	Rm 108, bathroom	Rm 107, bathroom	Rm 109, bathroom	Boys LR, coach sink	Custodial outlet 120	Rm 144, class sink	Boiler room	
Results	23.10	39.90	28.80	28.60	30.50	24.60	22.10	33.00	
Remediation	New faucet	New faucet	New faucet	New faucet	Install pending	Signage	New faucet	Flushing process	
Results	TBD	TBD	TBD	TBD	TBD	NA	TBD	TBD	
Back in use						12/1/16			
Location	Girl's coach sink	Girl's coach shower	Outdoor-by 137	Outdoor-by-143	Outdoor-by-130				
Results	16.60	535.00	214.00	557.00	18.50				
Remediation	Install pending	Signage	Signage	Signage	Signage				
Results	TBD	NA	NA	NA	NA				
Back in use		12/1/16	12/1/16	12/1/16	12/1/16				
Forest									
Location	Rm 20, sink #3	Rm 18, sink	Rm 1, sink	Rm 38, sink	Rm 36, sink	Rm 39, sink	Boys coach office	Staff kitchen lav	
Test results	36.10	17.80	18.20	17.30	20.00	21.40	19.90	18.00	
Remediation	Replace fixture	Replace fixture	Replace fixture	Pending	Replace fixture, stops	Replace fixture	Pending	New faucet	
Results	13.50	4.71	12.70	Pending	Pending	12.40	Pending	Pending	
Back in use	11/1/2016	11/1/2016	11/1/2016			11/1/2016			
Back in use									
Location	Kitchen sink-west	Kitchen sink-dish	Outdoor-by rm 16	Outdoor-by rm 1	Outdoor-by rm 2				
Test results	15.40	26.00	30.10	95.10	184.00				
Remediation	Pending	Pending	Signage	Signage	Signage				
Results			NA	NA	NA				
Back in use			11/2/2016	11/2/2016	11/2/2016				

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Heim								
Location	Rm 109, sink	Rm 112	Staff kitchen lav	Custodial shower	Outdoor-courtyard	Outdoor-by 147	Outdoor-by 106	Outdoor-by office
Test results	15.60	687.00	15.40	53.30	17.00	45.20	95.80	73.40
Remediation	New faucet	Removed	New faucet	Signage	Signage	Signage	Signage	Signage
Results	Pending	NA	Pending	NA	NA	NA	NA	NA
Back in use		NA		12/6/16	12/6/16	12/6/16	12/6/16	12/6/16
Location	Outdoor-by generator	Kitchen-custodial	Outdoor-by 132	Outdoor-by-142	Rm 188, music			
Test results	61.30	1390.00	122.00	1210.00	21.20			
Remediation	Signage	Removed	Signage	Signage	New faucet			
Results	NA	NA	NA	NA	Pending			
Back in use	12/6/16	NA	12/6/16	12/6/16				
Maple East								
Location	Rm 39, sink	Rm 39, fountain	Rm 29, sink #3	Outdoor-courtyard	Library office sink	Rm 67. sink	Rm 56c, sink	Outdoor-by-Main
Test results	27.00	24.80	932.00	117.00	32.40	240.00	27.40	36.20
Remediation	New faucet	New fountain	Pending	Signage	New faucet	New faucet	New faucet	Signage
Results	Pending	Pending	Pending	NA	Pending	Pending	Pending	NA
Back in use				12/2/16				12/2/16
Location	Outdoor-by-20	Boiler rm eyewash	Rm 56-c Sink	Rm 49, girls shower	Rm 46, sink	Rm 46, fountain		
Test results	98.50	75.20	41.10	58.80	15.90	24.50		
Remediation	Signage	Signage	New faucet	New faucet	New faucet	New fountain		
Results	NA	NA	Pending	Pending	Pending	Pending		
Back in use	12/2/2016	12/2/2016						

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Transit middle								
Location	Science - A110 - #1	Library office sink	Outside faucet A105	Boy's LR shower 1	Boy's LR shower 2	Boy's LR shower 6	Boy's LR shower 7	Boy's LR shower 8
Test results	19.7	24	87	63.6	22.6	29.2	67.2	16
Remediation	Signage	Change faucet	Signage	Signage	Signage	Signage	Signage	Signage
Location	Boy's LR shower 9	Girl's coach shower	Girl's LR shower 2	Girl's LR shower 3	Girl's LR shower 4	Girl's LR shower 9	Pool chem eyewash	Pool chem hose faucet
Test results	15.7	68.1	19.9	43.2	66.2	45.8	39.8	17
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Location	Pool deck faucet 1	Pool deck faucet 2	Tech rm 108 - #4	Tech rm 108 - #6	Tech rm 108 - #7	Science B123-2	Science B123 - 3	
Test results	83	24.4	21.3	158	16.6	80.7	32.5	
Remediation	Signage	Signage	TBD	TBD	TBD	Signage	Signage	

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

East high								
Location	Science- 224 -sink 3	Science-223-sink 3	Science-223-sink #4	Science-223-sink #5	Science- 222-sink 1	Science-222-sink 3	Science-222-sink 4	Science-222 sink 5
Test results	29.8	37.9	19.4	29.8	32.9	29.9	22.7	47
Remediation	signage	signage	signage	signage	signage	signage	signage	signage
Back-in-service								
Location	Science-222 Sink 6	2nd Fl Boys hose bib	2nd Fl Girl's hose bib	Boy's LR shower 12	2nd Fl Science prep	Boys change hose bid	Boys change shower 6	Girls shower hose bid
Test results	31.4	174	552	33.1	21.9	42.7	21.2	368
Remediation	signage	signage	signage	signage	signage	signage	signage	signage
Back-in-service								
Location	Girls Shower #6	Pool hose bid 1	Science-222-sink 7	3rd Fl Girl hose faucet	3rd Fl Girl hose faucet	3rd Fl Girl hose faucet	Outside faucet by Sports	Outside faucet by music
Test results	51.9	61.9	21.4	1750	1300	1950	22.1	25.6
Remediation	signage	signage	signage	signage	signage	signage	signage	signage
Back-in-service								
Location	Outside faucet west red	Outside faucet west or	Outside faucet by 131	Tech Room 119	Science 325 #1	Science 325 #8	Science 325 eye wash	Science 324 eye wash
Test results	1180	69.7	71.8	230	35.4	36.6	18.1	32.7
Remediation	signage	signage	signage	TBD	signage	signage	signage	signage
Back-in-service								
Location	Science 322 #2	Science 322 eye wash	Science-222 Sink 7	Pool chem hose bib	Pool chem eye wash	Men fac lav Blue commons hose bib	Womens fac lav Blue commons hose bib	Kitchen sink #5
Test results	50.7	19.6	21.4	60.4	316	201	2200	40.7
Remediation	signage	signage	signage	signage	signage	signage	signage	Replacement
Back-in-service								
Location	Kitchen sink #6	Hose bib room 106	Photo sink4 rm 117	Photo sink6 rm 117	Boy lav orange hose bib	Girl Red lav hose bib	Science 119 sink 1	Science 119 sink 2
Test results	22.2	895	57.9	63	336	221	70.2	27.9
Remediation	Replacement	signage	signage	signage	signage	signage	signage	signage
Back-in-service								
Location	Science 119 sink 3	Science 119 sink 4	Science 119 sink 5	Science 113 sink	Men's lav - aud - faucet	Girl's coach office sink	Girl's LR hose bib	Girl's LR shower 1
Test results	71.1	28.6	16.6	15.9	29.2	20.1	272	82.5
Remediation	signage	signage	signage	signage	signage	signage	signage	signage
Back-in-service								
East high								
Location	Girl's LR shower 2	Girl's LR shower 3	Girl's LR shower 4	Girl's LR shower 5	Girl's LR shower 6	Girl's LR shower 7	Girl's LR shower 8	Girl's LR shower 9

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Test results	68.9	1970	85.2	73	186	101	154	58.4
Remediation	signage	signage	signage	signage	signage	signage	signage	signage
Back-in-service								

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

South high								
Location	Boiler room	Science E-1	Science E-2B	Mens lav - E-2 #2	Science E-3 - 2	Science E-3 - 3	Science E-3 - 4	Science E-3 - 5
Test results	29.9	18.8	41.3	28.9	115	57.7	38	37.2
Remediation	Signage	Signage	Signage	change faucet	Signage	Signage	Signage	Signage
Results								
Back in use								
Location	Science E-3 - 6	Science E-3 - 8	Science E-3 - 9	Science - E-3 Eye	Science - E-3B	Science - E-4 - 2	Science - E-4 - 3	Science - E-4 - 4
Test results	32.7	90.4	89.6	58.9	245	111	78.1	32.9
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Back in use								
Location	Science - E-4 - 5	Science - E-4 - 7	Science - E-4 - 8	Science - E-4 - Eye	Science - E-5 -1	Science - E-5 -2	Science - E-5 -3	Science - E-5 - 4
Test results	53	64.1	65.2	18.4	21.1	27.3	26	23.4
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Back in use								
Location	Science - E-5 B sink	Science E-7 - 2	Science E-7 - Eye	Science E-7 - Shower	Science EB-sink	Science E8 - 2	Old gym girl's shower 13	Greenhouse hose bib2
Test results	159	26	39.9	31.2	22.5	19.7	1120	197
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Back in use								
Location	New gym B- LR shower1	Old gym B-LR shower8	Old gym B-LR shower9	Outside hose bib 389	Science chem cab hose	Greenhouse hose bib1	Outside faucet - E-5	
Test results	2380	25.4	323	67.2	111	119	92.5	
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	
Back in use								
Location	Old gym LR shower 3	Old gym LR shower 4	Old gym LR shower 5	Old gym LR shower 6	Old gym LR shower 7	Old gym Squad rm sink	Old gym LR shower 1	Old gym LR shower 2
Test results	129	90.2	39.6	57.1	111	109	75.1	26.6
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Back in use								
Location	Old gym SR shower1	Old gym SR shower2	Old gym SR shower3	Old gym SR shower4	Old gym SR shower5	Old gym SR shower6	Old gym SR shower7	Old gym SR shower8
Test results	84.4	82.8	345	173	99.7	33.6	41.1	72.3
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Back in use								
South high								
Location	Old gym SR shower9	Old gym SR shower10	Old gym SR shower11	Old gym SR shower12	Tech room 129 sink 1	Tech room 129 sink 3	Tech room 129 sink 4	Girl's coach shower
Test results	382	67	68.1	328	134	43	183	31.2

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Back in use									
Location	SR custodial hose bib	Old gym fountain	Boy's lav hose bib 107	Girl's LR hose bib	Basement custodial	New gym BoyLR shwr 2	New gym BoyLR shwr 3	New gym BoyLR shwr 4	
Test results	20.7	37.5	766	149	111	62.7	112	188	
Remediation	Signage	Replacement	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Back in use									
Location	New gym BoyLR shwr 5	New gym BoyLR shwr 6	New gym BoyLR shwr 7	New gym BoyLR shwr 8	New gym BoyLR shwr 9	Boy's coach office NG shw	Custodial sink by 142	New gym GirlLR shwr1	
Test results	18.5	123	89.3	115	23.6	27	18.8	444	
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Back-in use									
Location	New gym GirlLR shwr2	New gym GirlLR shwr3	New gym GirlLR shwr4						
Test results	426	5110	1180						
Remediation	Signage	Storage area-sign	Storage area-sign						
Back in use									

AIM building

Location	Science - 1	Science - 2	Science - 4	Science - 5	Sceince eyewash	Outside faucet-013	Outside faucet - 10		
Test results	20.4	31.3	86.4	60.2	26.3	31.5	132		
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage		

District office

Location	
Test results	

Hose bib: A hose bib is a faucet that is used to connect a hose for cleaning purposes. These faucets are not meant for use as a source of drinking water.