

Williamsville CSD					12/28/2016			
Locations of Water Test Samples Greater than 15 ppb				<b>NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.</b>				
<b><u>Country Parkway</u></b>								
Location	Rm 119, fountain	Rm 121, fountain	Rm 125, fountain	Staff kitchen lav	IMC, hose bib	Custodial closet #2	Outdoor -Boiler rm	Outdoor-by 122
Results	16.70	17.30	20.20	27.30	13400.00	39.00	131.00	232.00
Remediation	Replaced fountain	Replaced fountain	Replaced fountain	New faucet	Signage	Signage	Signage	Signage
Results	27.6	13.2	20.1	Pending	NA	NA	NA	NA
Back in use	TBD	11/1/2016	TBD	TBD	12/6/16	10/24/16	12/6/16	12/6/16
Location	Outdoor-by115	Outdoor-by108	Outdoor-by 105	Outdoor-by100	Outdoor-by-Office	Girls LR shower	Boys-LR shower	Custodial by rm 100
Results	59.10	135.00	223.00	139.00	198.00	53.90	16.70	27.20
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Results	NA	NA	NA	NA	NA	NA	NA	NA
Back in use	12/6/16	12/6/16	12/6/16	12/6/16	12/6/16	12/6/16	12/6/16	12/6/16
Location	Library office sink	Rm 104, sink	Rm 104, fountain	Rm 106, sink	Rm 106, fountain	Rm 107, sink	Rm 108, sink	Rm 110, sink
Results	17.00	39.30	457.00	20.30	17.60	21.10	26.30	15.90
Remediation	New faucet	New faucet	New fountain	New faucet	New faucet	New faucet	New faucet	New faucet
Results	12.90	Pending	Pending	Pending	Pending	12.20	25.90	20.66
Back in use	12/16/16	TBD	TBD	TBD	TBD	12/16/16	TBD	TBD
Location	Rm 117, sink	Rm 117, fountain	Rm 118, sink	Rm 118, fountain	Speech office sink	Outdoor-by-120	Outdoor-by-106	
Results	18.10	23.70	22.10	27.00	18.30	77.30	30.20	
Remediation	New faucet	New fountain	New faucet	New fountain	New faucet	Signage	Signage	
Results	Pending	Pending	Pending	Pending	12.30	NA	NA	
Back in use	TBD	TBD	TBD	TBD	12/16/16	12/6/16	12/6/16	

Locations of Water Test Samples Greater than 15 ppb

***NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.***

<b><u>Dodge</u></b>								
Location	Rm 106, bathroom	Rm 108, bathroom	Rm 107, bathroom	Rm 109, bathroom	Boys LR, coach sink	Custodial outlet 120	Rm 144, class sink	Boiler room
Results	23.10	39.90	28.80	28.60	30.50	24.60	22.10	33.00
Remediation	New faucet	New faucet	New faucet	New faucet	Install pending	Signage	New faucet	Flushing process
Results	TBD	TBD	TBD	TBD	TBD	NA	TBD	TBD
Back in use	TBD	TBD	TBD	TBD	TBD	12/1/16	TBD	TBD
Location	Girl's coach sink	Girl's coach shower	Outdoor-by 137	Outdoor-by-143	Outdoor-by-130			
Results	16.60	535.00	214.00	557.00	18.50			
Remediation	Install pending	Signage	Signage	Signage	Signage			
Results	TBD	NA	NA	NA	NA			
Back in use	TBD	12/1/16	12/1/16	12/1/16	12/1/16			
<b><u>Forest</u></b>								
Location	Rm 20, sink #3	Rm 18, sink	Rm 1, sink	Rm 38, sink	Rm 36, sink	Rm 39, sink	Boys coach office	Staff kitchen lav
Test results	36.10	17.80	18.20	17.30	20.00	21.40	19.90	18.00
Remediation	Replace fixture	Replace fixture	Replace fixture	Pending	Replace fixture, stops	Replace fixture	Replace fixture	New faucet
Results	13.50	4.71	12.70	Pending	15.30	12.40	Pending	Pending
Back in use	11/1/2016	11/1/2016	11/1/2016	TBD	TBD	11/1/2016	TBD	TBD
Back in use								
Location	Kitchen sink-west	Kitchen sink-dish	Outdoor-by rm 16	Outdoor-by rm 1	Outdoor-by rm 2			
Test results	15.40	26.00	30.10	95.10	184.00			
Remediation	Replace fixture	Replace fixture	Signage	Signage	Signage			
Results	TBD	TBD	NA	NA	NA			
Back in use	TBD	TBD	11/2/2016	11/2/2016	11/2/2016			

Locations of Water Test Samples Greater than 15 ppb

***NOTE: Fixture replacement is being prioritized by our facility staff and is occuring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.***

<b>Heim</b>								
Location	Rm 109, sink	Rm 112	Staff kitchen lav	Custodial shower	Outdoor-courtyard	Outdoor-by 147	Outdoor-by 106	Outdoor-by office
Test results	15.60	687.00	15.40	53.30	17.00	45.20	95.80	73.40
Remediation	New faucet	Removed	New faucet	Signage	Signage	Signage	Signage	Signage
Results	Pending	NA	21.80	NA	NA	NA	NA	NA
Back in use	TBD	NA	TBD	12/6/16	12/6/16	12/6/16	12/6/16	12/6/16
Location	Outdoor-by generator	Kitchen-custodial	Outdoor-by 132	Outdoor-by-142	Rm 188, music			
Test results	61.30	1390.00	122.00	1210.00	21.20			
Remediation	Signage	Removed	Signage	Signage	New faucet			
Results	NA	NA	NA	NA	17.50			
Back in use	12/6/16	NA	12/6/16	12/6/16	TBD			
<b>Maple East</b>								
Location	Rm 39, sink	Rm 39, fountain	Rm 29, sink #3	Outdoor-courtyard	Library office sink	Rm 67. sink	Rm 56c, sink	Outdoor-by-Main
Test results	27.00	24.80	932.00	117.00	32.40	240.00	27.40	36.20
Remediation	New faucet	New fountain	Pending	Signage	New faucet	New faucet	New faucet	Signage
Results	Pending	Pending	Pending	NA	104.00	23.40	Pending	NA
Back in use	TBD	TBD	TBD	12/2/16	TBD	TBD	TBD	12/2/16
Location	Outdoor-by-20	Boiler rm eyewash	Rm 56-c Sink	Rm 49, girls shower	Rm 46, sink	Rm 46, fountain		
Test results	98.50	75.20	41.10	58.80	15.90	24.50		
Remediation	Signage	Signage	New faucet	New faucet	New faucet	New fountain		
Results	NA	NA	Pending	Pending	Pending	Pending		
Back in use	12/2/2016	12/2/2016	TBD	TBD	TBD	TBD		

Locations of Water Test Samples Greater than 15 ppb

***NOTE: Fixture replacement is being prioritized by our facility staff and is occuring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.***

<b><u>Maple West</u></b>								
Location	Custodial by gym	Custodial-Bathroom	Custodial-shower	Custodial-by-Kitchen	Outdoor-by-124	Outdoor-by dock	Kitchen - cleaning	Rm 7, sink
Test results	20.90	20.60	138.00	30.30	41.10	255.00	82.40	38.40
Remediation	Signage	New faucet	Signage	Signage	Signage	Signage	New faucet	New faucet
Results	NA	17.80	NA	NA	NA	NA	85.90	9.70
Back in use	12/2/16	TBD	12/2/16	12/2/16	12/2/16	12/2/16	TBD	12/16/16
Location	Rm 113, sink #1	Library office sink	Athletic -girls shower	Athletic-boys-shower	Boiler rm eyewash	Outside-by-main	Outside-by-109	Hallway fountain-2
Test results	17.10	19.60	174.00	60.00	81.20	30.70	91.10	18.00
Remediation	New faucet	New faucet	Signage	New faucet	Signage	Signage	Signage	Pending
Results	11.50	17.30	NA	<1.0	NA	NA	NA	Pending
Back in use	12/16/16	TBD	12/2/16	12/16/16	12/2/16	12/2/16	12/2/16	TBD
<b><u>Casey middle</u></b>								
Location	Stage sink	Room 135 #3	Room 135 #4	Room 139 #1	Room 139A	Faculty lav sink 2	Girl's LR shower #2	Girl's LR shower #5
Test results	76.5	27.2	41.8	30.5	22.6	31.6	40.1	21.9
Remediation	TBD	TBD	TBD	TBD	TBD	TBD	Signage	Signage
Back in use	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBd
Location	Girl's LR shower #6	Kitchen lav sink	Custodial Mech	Outside faucet - 131	Outside hose bib 140	Outside hose bib 144	Hose bib pool rm	Eye wash pool rm
Test results	16.9	17.8	52.7	24.6	27.7	605	44.8	85.9
Remediation	Signage	TBD	Signage	Signage	Signage	Signage	Signage	Signage
Back in use	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD

Locations of Water Test Samples Greater than 15 ppb

***NOTE: Fixture replacement is being prioritized by our facility staff and is occuring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.***

<b>Heim middle</b>								
Location	Hec- outlet for washer	Science-B-14-#2	Science-B-14-#3	Science-C-11 #3	Science-C-11 #2	Science-C-13 #4	Sciecne D10 - sink 1	Science D10 sink 2
Test results	32.7	15.3	17.4	71.9	18.1	25.8	323	20
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Back in svc.	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD
Location	Science D10 sink 3	Science D10 sink 4	Science D10 sink 5	Science D10 sink 6	Science D10 sink 9	Science D8 sink 1	Science D8 sink2	Science D7 sink1
Test results	867	124	65.4	1050	449	52.3	245	27.5
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Back in svc.	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD
Location	Science D7 sink 4	D7 washing machine	Tech D6 sink 1	Tech D6 sink 2	Boys LR sink 2	Gym fountain	Girls LR shower 8 A-13 sink 1	
Test results	20	30.5	41.8	87.6	17.4	44	34.6	44.3
Remediation	Signage	Signage	Signage	Signage	Signage	Replacement	Signage	Faucet replacement
Back in svc.	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD
Location	Men's Lav by Aud sink 1	Custodial sink kitchen	Facility fan room	Hose bib pool	Hose bib outside	Hose bib courtyard A	Hose bib courtyard B	Hose bib courtyard C
Test results	19.70	20.30	132.00	26.40	31.60	62.7	2310.00	5880
Remediation	Faucet replacement	Faucet replacement	Signage	Signage	Signage	Signage	Signage	Signage
Back in svc.	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD
Location	Boiler rm eye wash	Outside hose bib D10	Outside hose bib aud	Outside hose bib C-11	Outside hose bib C-2	Outside hose bib B-11	Outside hose bib B-2	Outside hose bib A-10
Test results	57.20	36.20	112.00	119.00	93.70	46.3	62.00	156
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Back in svc.	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD
Location	Outside hose bib A-2	Outside hose bib flag						
Test results	193.00	299.00						
Remediation	Signage	Signage						
Back in svc.	TBD	TBD						

Locations of Water Test Samples Greater than 15 ppb

***NOTE: Fixture replacement is being prioritized by our facility staff and is occuring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.***

<b>Mill middle</b>								
Location	Custodial sink M-4	Girl's LR shower #1	Girl's LR shower #2	Girl's LR shower #3	Girl's LR shower #4	Girl's LR shower #8	Girl's LR shower #9	Girl's LR shower #10
Test results	15.2	41.3	38.3	35.9	22.7	63.6	43.3	65.6
Remediation	signage	signage	signage	signage	signage	signage	signage	signage
Back in svc.	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD
Location	Girl's LR shower #11	Girl's LR shower #12	Girl's LR shower #13	Girl's LR shower #14	Girl's LR shower #15	Girl's LR shower #16	Kitchen dish sprayhead	Pool filter faucet
Test results	35.6	26.4	28.8	28.9	25.8	32.8	21.6	35.9
Remediation	signage	signage	signage	signage	signage	signage	signage	signage
Back in svc.	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD
Location	Loading dock Faucet	Science-C4 sink1	Science C4 sink 2	Science C6-sink	Science C-8 sink	Custodial sink c-11	Science C-11 sink	Sceince C-10 sink
Test results	18.9	22.6	32	30.5	55.5	18.3	43.2	23.1
Remediation	signage	signage	signage	signage	signage	signage	signage	signage
Back in svc.	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD
Location	Science C-13 sink	Room E-3 Tchr sink	Room E-2 sink 3	Room E-7 sink 1	Boy's Tchr Shower	Boy's LR Shower 2	Boy's LR Shower 3	Boy's LR shower 4
Test results	42.8	17	18.4	75.6	27.1	34.5	43.5	23.8
Remediation	signage	signage	signage	signage	signage	signage	signage	signage
Back in svc.	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD
Location	Boy's LR Shower 5	Boy's LR Shower 6	Boy's LR Shower 7	Boy's LR Shower 8	Boy's LR Shower 9	Boy's LR Shower 10	Boy's LR Shower 11	Boy's LR shower 12
Test results	27.4	34.5	91.9	66.9	34.3	111	40.1	47.2
Remediation	signage	signage	signage	signage	signage	signage	signage	signage
Back in svc.	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD
Location	Boy's LR Shower 13	Boy's LR Shower 14	Boy's LR Shower 15	Boy's LR Shower 16	Room C-4 Tchr sink	Boiler room sink	Room A-1 sink	Science A-2 sink1
Test results	43.4	35.6	73.8	70.6	43.8	895	20.1	28.9
Remediation	signage	signage	signage	signage	TBD	signage	TBD	TBD
Back in svc.	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD
Location	Science A-2 sink 2	Science A-2 sink 3	Science A-2 sink 4	Science A-2 office	Science A-4 sink 2	Science A-4 sink 3	Science A-4 sink 4	Classroom A-6 sink
Test results	49.4	73.1	95.9	44	52.1	60.7	65.7	42.8
Remediation	signage	signage	signage	signage	signage	signage	signage	Replace faucet
Back in svc.	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD

Locations of Water Test Samples Greater than 15 ppb

***NOTE: Fixture replacement is being prioritized by our facility staff and is occuring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.***

<b>Mill middle</b>								
Location	Classroom A-8 sink	Classroom A-9 sink	Classroom A-11 sink	Classroom A-10 sink	Classroom A-13 sink	Library office sink	Boy's Lav by A-11	Custodial by library
Test results	39.4	59.2	27.5	26	33.7	21.9	20.2	60.3
Remediation	TBD	TBD	TBD	TBD	TBD	Replace faucet	Replace faucet	signage
Back in svc.	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD
Location	Science B-2 sink1	Science B-2 sink2	Science B-2 sink3	Science B2 Tchr office 1	Science B2 Tchr office 2	Science B-4 sink1	Science B-4 sink2	Science B-4 sink3
Test results	40.3	71.6	69.2	73.8	57.6	33.5	17.7	70.9
Remediation	signage	signage	signage	signage	signage	signage	signage	signage
Back in svc.	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD
Location	Classroom B-6 sink	Classroom B-8 sink	Science B-9 sink	Classroom B-11 sink	Classroom B-10 sink	Classroom B-13 sink	IMC sink	Hose bib boiler rm
Test results	19.7	18.5	21.7	36.3	32.8	32.3	16	63.1
Remediation	TBD	TBD	Replace faucet	TBD	TBD	TBD	Replace faucet	signage
Back in svc.	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD
Location	Hose bib pool mech rm	Science B-4 sink4						
Test results	70.3	27						
Remediation	signage	signage						
Back in svc.	TBD	TBD						

Locations of Water Test Samples Greater than 15 ppb

**NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.**

<b>Transit middle</b>								
Location	Science - A110 - #1	Library office sink	Outside faucet A105	Boy's LR shower 1	Boy's LR shower 2	Boy's LR shower 6	Boy's LR shower 7	Boy's LR shower 8
Test results	19.7	24	87	63.6	22.6	29.2	67.2	16
Remediation	Signage	Change faucet	Signage	Signage	Signage	Signage	Signage	Signage
Back in svc.	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD
Location	Boy's LR shower 9	Girl's coach shower	Girl's LR shower 2	Girl's LR shower 3	Girl's LR shower 4	Girl's LR shower 9	Pool chem eyewash	Pool chem hose faucet
Test results	15.7	68.1	19.9	43.2	66.2	45.8	39.8	17
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Back in svc.	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD
Location	Pool deck faucet 1	Pool deck faucet 2	Tech rm 108 - #4	Tech rm 108 - #6	Tech rm 108 - #7	Science B123-2	Science B123 - 3	Science B229 sink 1
Test results	83	24.4	21.3	158	16.6	80.7	32.5	15.6
Remediation	Signage	Signage	TBD	TBD	TBD	Signage	Signage	Signage
Back in svc.	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD
Location	Science B229 sink 4	Science B229 sink 5	Science B229 sink 6	Science B229 sink 8	Science B229 sink 9	Science B229 sink 10	Science B229 sink 11	Science B229 sink 12
Test results	21	28.8	16.9	19.2	24.4	39.6	16.8	27.8
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Back in svc.	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD
Location	Science B229 eyewash	Science B227 sink 1	Science B212 sink 1	Science B212 sink 2	Science B212 sink 3	Science B214 sink 2	Science B214 sink 3	Science B214 sink 4
Test results	442	2490	27.1	16	23	221	37.6	82.3
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Back in svc.	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD
Location	Science B214 sink 5	Science B214 sink 6	Science B214 sink 7	Science B214 sink 8	Science B214 sink 9	Science B214 sink 10	Custodial sink by 214	Room A214 tcher sink
Test results	44.5	53.9	23.2	41.8	35.5	25.6	52.4	39.3
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Change faucet
Back in svc.	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD
Location	Outside hose bib B123	Outside hose bib A105						
Test results	37.1	87						
Remediation	Signage	Signage						
Back in svc.	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD



Locations of Water Test Samples Greater than 15 ppb

**NOTE: Fixture replacement is being prioritized by our facility staff and is occuring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.**

<b>East high</b>								
Location	Science- 224 -sink 3	Science-223-sink 3	Science-223-sink #4	Science-223-sink #5	Science- 222-sink 1	Science-222-sink 3	Science-222-sink 4	Science-222 sink 5
Test results	29.8	37.9	19.4	29.8	32.9	29.9	22.7	47
Remediation	signage	signage	signage	signage	signage	signage	signage	signage
Back in svc.	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD
Location	Science-222 Sink 6	2nd Fl Boys hose bib	2nd Fl Girl's hose bib	Boy's LR shower 12	2nd Fl Science prep	Boys change hose bid	Boys change shower 6	Girls shower hose bid
Test results	31.4	174	552	33.1	21.9	42.7	21.2	368
Remediation	signage	signage	signage	signage	signage	signage	signage	signage
Back in svc.	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD
Location	Girls Shower #6	Pool hose bid 1	Science-222-sink 7	3rd Fl Girl hose faucet	3rd Fl Girl hose faucet	3rd Fl Girl hose faucet	Outside faucet by Sports	Outside faucet by music
Test results	51.9	61.9	21.4	1750	1300	1950	22.1	25.6
Remediation	signage	signage	signage	signage	signage	signage	signage	signage
Back in svc.	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD
Location	Outside faucet west red	Outside faucet west or	Outside faucet by 131	Tech Room 119	Science 325 #1	Science 325 #8	Science 325 eye wash	Science 324 eye wash
Test results	1180	69.7	71.8	230	35.4	36.6	18.1	32.7
Remediation	signage	signage	signage	TBD	signage	signage	signage	signage
Back in svc.	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD
Location	Science 322 #2	Science 322 eye wash	Science-222 Sink 7	Pool chem hose bib	Pool chem eye wash	Men fac lav Blue commons	Womens fac lav Blue commons	Kitchen sink #5
Test results	50.7	19.6	21.4	60.4	316	hose bib 201	hose bib 2200	40.7
Remediation	signage	signage	signage	signage	signage	signage	signage	Replacement
Back in svc.	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD
Location	Kitchen sink #6	Hose bib room 106	Photo sink4 rm 117	Photo sink6 rm 117	Boy lav orange hose bib	Girl Red lav hose bib	Science 119 sink 1	Science 119 sink 2
Test results	22.2	895	57.9	63	336	221	70.2	27.9
Remediation	Replacement	signage	signage	signage	signage	signage	signage	signage
Back in svc.	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD
Location	Science 119 sink 3	Science 119 sink 4	Science 119 sink 5	Science 113 sink	Men's lav - aud - faucet	Girl's coach office sink	Girl's LR hose bib	Girl's LR shower 1
Test results	71.1	28.6	16.6	15.9	29.2	20.1	272	82.5
Remediation	signage	signage	signage	signage	signage	signage	signage	signage
Back in svc.	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD
<b>East high</b>								
Location	Girl's LR shower 2	Girl's LR shower 3	Girl's LR shower 4	Girl's LR shower 5	Girl's LR shower 6	Girl's LR shower 7	Girl's LR shower 8	Girl's LR shower 9

Locations of Water Test Samples Greater than 15 ppb

*NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.*

Test results	68.9	1970	85.2	73	186	101	154	58.4
Remediation	signage	signage	signage	signage	signage	signage	signage	signage
Back in service	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD

Locations of Water Test Samples Greater than 15 ppb

***NOTE: Fixture replacement is being prioritized by our facility staff and is occuring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.***

<b>North high</b>								
Location	Custodial basement #1	Basement storeroom	Hall fountain A-146	Career Center #1	Career Center #2	Science A-113 #2	Science A-120 #9	Science A119 #5
Test results	57.3	138	20.1	40.5	55.2	26	85.1	19.2
Remediation	Signage	Signage	New fountain	Change faucet	Change faucet	Signage	Signage	Signage
Back in service	TBD	TBD	No down time	TBD	TBD	TBD	TBD	TBD
Location	Science A-119 #7	Science A-119 # 8	Science A-119 #9	Hall Fountain A-120	Outside hose bib 380	Outside hose bib B104	Outside hose bib B135	Outside hose bib B128
Test results	19.6	15.2	22.9	83.8	213	38	179	58
Remediation	Signage	Signage	Signage	New fountain	Signage	Signage	Signage	Signage
Back in service	TBD	TBD	TBD	No down time	TBD	TBD	TBD	TBD
Location	Outside hose bib A152	Outside hose bib A103	Outside hose bib C108	Hose bib tech dust col	Outside hose bib AIM	Hose bib by fountain	Girl pool LR Hose bib	Boys pool LR hose bib
Test results	74.1	63.1	69.9	69	64.2	61.7	77.7	69.5
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Back in service	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD
Location	Girl coach office sink	Auto shop hose bib	Custodial sink - C-162	Faculty lav - 130 sink 2	Faculty lav - 130 sink 3	Boy's LR shower 6	Girt's LR shower 1	Girl's LR shower 2
Test results	142	28.9	19.5	17.8	43.1	54.4	65.9	52.3
Remediation	change faucet	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Back in service	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD
Location	Girt's LR shower 3	Girt's LR shower 5	Science B128 sink 3	Science C108 sink4	Room C106 eye wash1	Room C106 eye wash2	Health office eye wash	Pool pump eye wash
Test results	65.3	160	42	90	24.3	44.9	237	18.9
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Back in service	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD

Locations of Water Test Samples Greater than 15 ppb

***NOTE: Fixture replacement is being prioritized by our facility staff and is occuring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.***

<b>South high</b>								
Location	Boiler room	Science E-1	Science E-2B	Mens lav - E-2 #2	Science E-3 - 2	Science E-3 - 3	Science E-3 - 4	Science E-3 - 5
Test results	29.9	18.8	41.3	28.9	115	57.7	38	37.2
Remediation	Signage	Signage	Signage	change faucet	Signage	Signage	Signage	Signage
Results	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD
Back in use	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD
Location	Science E-3 - 6	Science E-3 - 8	Science E-3 - 9	Science - E-3 Eye	Science - E-3B	Science - E-4 - 2	Science - E-4 - 3	Science - E-4 - 4
Test results	32.7	90.4	89.6	58.9	245	111	78.1	32.9
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Back in use	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD
Location	Science - E-4 - 5	Science - E-4 - 7	Science - E-4 - 8	Science - E-4 - Eye	Science - E-5 -1	Science - E-5 -2	Science - E-5 -3	Science - E-5 - 4
Test results	53	64.1	65.2	18.4	21.1	27.3	26	23.4
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Back in use	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD
Location	Science - E-5 B sink	Science E-7 - 2	Science E-7 - Eye	Science E-7 - Shower	Science EB-sink	Science E8 - 2	Old gym girl's shower 13	Greenhouse hose bib2
Test results	159	26	39.9	31.2	22.5	19.7	1120	197
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Back in use	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD
Location	New gym B- LR shower1	Old gym B-LR shower8	Old gym B-LR shower9	Outside hose bib 389	Science chem cab hose	Greenhouse hose bib1	Outside faucet - E-5	
Test results	2380	25.4	323	67.2	111	119	92.5	
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	
Back in use	TBD	TBD	TBD	TBD	TBD	TBD	TBD	
Location	Old gym LR shower 3	Old gym LR shower 4	Old gym LR shower 5	Old gym LR shower 6	Old gym LR shower 7	Old gym Squad rm sink	Old gym LR shower 1	Old gym LR shower 2
Test results	129	90.2	39.6	57.1	111	109	75.1	26.6
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Back in use	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD
Location	Old gym SR shower1	Old gym SR shower2	Old gym SR shower3	Old gym SR shower4	Old gym SR shower5	Old gym SR shower6	Old gym SR shower7	Old gym SR shower8
Test results	84.4	82.8	345	173	99.7	33.6	41.1	72.3
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Back in use	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD
<b>South high</b>								
Location	Old gym SR shower9	Old gym SR shower10	Old gym SR shower11	Old gym SR shower12	Tech room 129 sink 1	Tech room 129 sink 3	Tech room 129 sink 4	Girl's coach shower
Test results	382	67	68.1	328	134	43	183	31.2

Locations of Water Test Samples Greater than 15 ppb

***NOTE: Fixture replacement is being prioritized by our facility staff and is occuring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.***

Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Back in use	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD
Location	SR custodial hose bib	Old gym fountain	Boy's lav hose bib 107	Girl's LR hose bib	Basement custodial	New gym BoyLR shwr 2	New gym BoyLR shwr 3	New gym BoyLR shwr 4
Test results	20.7	37.5	766	149	111	62.7	112	188
Remediation	Signage	Replacement	Signage	Signage	Signage	Signage	Signage	Signage
Back in use	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD
Location	New gym BoyLR shwr 5	New gym BoyLR shwr 6	New gym BoyLR shwr 7	New gym BoyLR shwr 8	New gym BoyLR shwr 9	Boy's coach office NG shw	Custodial sink by 142	New gym GirlLR shwr1
Test results	18.5	123	89.3	115	23.6	27	18.8	444
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Back in service	TBD	TBD	TBD	TBD	TBD	TBD	TBD	TBD
Location	New gym GirlLR shwr2	New gym GirlLR shwr3	New gym GirlLR shwr4					
Test results	426	5110	1180					
Remediation	Signage	Storage area-sign	Storage area-sign					
Back in use	TBD	TBD	TBD					

**AIM building**

Location	Science - 1	Science - 2	Science - 4	Science - 5	Sceince eyewash	Outside faucet-013	Outside faucet - 10
Test results	20.4	31.3	86.4	60.2	26.3	31.5	132
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Back in use	TBD	TBD	TBD	TBD	TBD	TBD	TBD

**District office**

Location
Test results

Hose bib: A hose bib is a faucet that is used to connect a hose for cleaning purposes. These faucets are not meant for use as a source of drinking water.