

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

<u>Country Parkway</u>	<u>District has received all first round water sampling results</u>							
Location	Rm 119, fountain	Rm 121, fountain	Rm 125, fountain	Staff kitchen lav	IMC, hose bib	Custodial closet #2	Outdoor -Boiler rm	Outdoor-by 122
Results	16.70	17.30	20.20	27.30	13400.00	39.00	131.00	232.00
Remediation	Replaced fountain	Replaced fountain	Replaced fountain	New faucet	Signage	Signage	Signage	Signage
Results	Pending	13.2	Pending	Pending	NA	NA	NA	NA
Back in use		11/1/2016			12/6/16	10/24/16	12/6/16	12/6/16
Location	Outdoor-by115	Outdoor-by108	Outdoor-by 105	Outdoor-by100	Outdoor-by-Office	Girls LR shower	Boys-LR shower	Custodial by rm 100
Results	59.10	135.00	223.00	139.00	198.00	53.90	16.70	27.20
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Results	NA	NA	NA	NA	NA	NA	NA	NA
Back in use	12/6/16	12/6/16	12/6/16	12/6/16	12/6/16	12/6/16	12/6/16	12/6/16
Location	Library office sink	Rm 104, sink	Rm 104, fountain	Rm 106, sink	Rm 106, fountain	Rm 107, sink	Rm 108, sink	Rm 110, sink
Results	17.00	39.30	457.00	20.30	17.60	21.10	26.30	15.90
Remediation	New faucet	New faucet	New fountain	New faucet	New faucet	New faucet	New faucet	New faucet
Results	Pending	Pending	Pending	Pending	Pending	Pending	Pending	Pending
Back in use								
Location	Rm 117, sink	Rm 117, fountain	Rm 118, sink	Rm 118, fountain	Speech office sink	Outdoor-by-120	Outdoor-by-106	
Results	18.10	23.70	22.10	27.00	18.30	77.30	30.20	
Remediation	New faucet	New fountain	New faucet	New fountain	New faucet	Signage	Signage	
Results	Pending	Pending	Pending	Pending	Pending	NA	NA	
Back in use						12/6/16	12/6/16	

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Dodge								
<u>Water sampling results</u>								
Location	Rm 106, bathroom	Rm 108, bathroom	Rm 107, bathroom	Rm 109, bathroom	Boys LR, coach sink	Custodial outlet 120	Rm 144, class sink	Boiler room
Results	23.10	39.90	28.80	28.60	30.50	24.60	22.10	33.00
Remediation	New faucet	New faucet	New faucet	New faucet	Install pending	Signage	New faucet	Flushing process
Results	TBD	TBD	TBD	TBD	TBD	NA	TBD	TBD
Back in use						12/1/16		
Location	Girl's coach sink	Girl's coach shower	Outdoor-by 137	Outdoor-by-143	Outdoor-by-130			
Results	16.60	535.00	214.00	557.00	18.50			
Remediation	Install pending	Signage	Signage	Signage	Signage			
Results	TBD	NA	NA	NA	NA			
Back in use		12/1/16	12/1/16	12/1/16	12/1/16			
Forest								
<u>Water sampling results</u>								
Location	Rm 20, sink #3	Rm 18, sink	Rm 1, sink	Rm 38, sink	Rm 36, sink	Rm 39, sink	Boys coach office	Staff kitchen lav
Test results	36.10	17.80	18.20	17.30	20.00	21.40	19.90	18.00
Remediation	Replace fixture	Replace fixture	Replace fixture	Pending	Replace fixture, stops	Replace fixture	Pending	New faucet
Results	13.50	4.71	12.70		Pending	12.40		Pending
Back in use	11/1/2016	11/1/2016	11/1/2016			11/1/2016		
Back in use								
Location	Kitchen sink-west	Kitchen sink-dish	Outdoor-by rm 16	Outdoor-by rm 1	Outdoor-by rm 2			
Test results	15.40	26.00	30.10	95.10	184.00			
Remediation	Pending	Pending	Signage	Signage	Signage			
Results			NA	NA	NA			
Back in use			11/2/2016	11/2/2016	11/2/2016			

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Heim	<u>d water sampling results</u>								
Location	Rm 109, sink	Rm 112	Staff kitchen lav	Custodial shower	Outdoor-courtyard	Outdoor-by 147	Outdoor-by 106	Outdoor-by office	
Test results	15.60	687.00	15.40	53.30	17.00	45.20	95.80	73.40	
Remediation	New faucet	Removed	New faucet	Signage	Signage	Signage	Signage	Signage	
Results	Pending	NA	Pending	NA	NA	NA	NA	NA	
Back in use		NA		12/6/16	12/6/16	12/6/16	12/6/16	12/6/16	
Location	Outdoor-by generator	Kitchen-custodial	Outdoor-by 132	Outdoor-by-142	Rm 188, music				
Test results	61.30	1390.00	122.00	1210.00	21.20				
Remediation	Signage	Removed	Signage	Signage	New faucet				
Results	NA	NA	NA	NA	Pending				
Back in use	12/6/16	NA	12/6/16	12/6/16					
Maple East	<u>d water sampling results</u>								
Location	Rm 39, sink	Rm 39, fountain	Rm 29, sink #3	Outdoor-courtyard	Library office sink	Rm 67. sink	Rm 56c, sink	Outdoor-by-Main	
Test results	27.00	24.80	932.00	117.00	32.40	240.00	27.40	36.20	
Remediation	New faucet	New fountain	Pending	Signage	New faucet	New faucet	New faucet	Signage	
Results	Pending	Pending	Pending	NA	Pending	Pending	Pending	NA	
Back in use				12/2/16					12/2/16
Location	Outdoor-by-20	Boiler rm eyewash	Rm 56-c Sink	Rm 49, girls shower	Rm 46, sink	Rm 46, fountain			
Test results	98.50	75.20	41.10	58.80	15.90	24.50			
Remediation	Signage	Signage	New faucet	New faucet	New faucet	New fountain			
Results	NA	NA	Pending	Pending	Pending	Pending			
Back in use	12/2/2016	12/2/2016							

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Mill middle

Location	Custodial sink M-4	Girl's LR shower #1	Girl's LR shower #2	Girl's LR shower #3	Girl's LR shower #4	Girl's LR shower #8	Girl's LR shower #9	Girl's LR shower #10
Test results	15.2	41.3	38.3	35.9	22.7	63.6	43.3	65.6
Remediation	signage	signage	signage	signage	signage	signage	signage	signage
Back-in service								

Location	Girl's LR shower #11	Girl's LR shower #12	Girl's LR shower #13	Girl's LR shower #14	Girl's LR shower #15	Girl's LR shower #16	Kitchen dish sprayhead	Pool filter faucet
Test results	35.6	26.4	28.8	28.9	25.8	32.8	21.6	35.9
Remediation	signage	signage	signage	signage	signage	signage	signage	signage

Location	Loading dock Faucet
Test results	18.9
Remediation	signange

Transit middle

Location	Science - A110 - #1	Library office sink	Outside faucet A105
Test results	19.7	24	87
Remediation			

Location
 Test results
 Remediation

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

East high

Location	Science- 224 -sink 3	Science-223-sink 3	Science-223-sink #4	Science-223-sink #5	Science- 222-sink 1	Science-222-sink 3	Science-222-sink 4	Science-222 sink 5
Test results	29.8	37.9	19.4	29.8	32.9	29.9	22.7	47
Remediation	signage	signage	signage	signage	signage	signage	signage	signage
Back-in-service								

Location	Science-222 Sink 6	2nd Fl Boys hose bib	2nd Fl Girl's hose bib	Boy's LR shower 12	2nd Fl Science prep	Boys change hose bid	Boys change shower 6	Girls shower hose bid
Test results	31.4	174	552	33.1	21.9	42.7	21.2	368
Remediation	signage	signage	signage	signage	signage	signage	signage	signage
Back-in-service								

Location	Girls Shower #6	Pool hose bid 1	Science-222-sink 7
Test results	51.9	61.9	21.4
Remediation	signage	signage	signage
Back-in-service			

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

North high

Location	Custodial basement #1	Basement storeroom	Hall fountain A-146	Career Center #1	Career Center #2	Science A-113 #2	Science A-120 #9	Science A119 #5
Test results	57.3	138	20.1	40.5	55.2	26	85.1	19.2
Remediation	Signage	Signage	New fountain	Change faucet	Change faucet	Signage	Signage	Signage
Back-in-service			No down time					

Location	Science A-119 #7	Science A-119 # 8	Science A-119 #9	Hall Fountain A-120
Test results	19.6	15.2	22.9	83.8
Remediation	Signage	Signage	Signage	New fountain
Back-in-service				No down time

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

South high

Location	Boiler room	Science E-1	Science E-2B	Mens lav - E-2 #2	Science E-3 - 2	Science E-3 - 3	Science E-3 - 4	Science E-3 - 5
Test results	29.9	18.8	41.3	28.9	115	57.7	38	37.2
Remediation	Signage	Signage	Signage		Signage	Signage	Signage	Signage
Results								
Back in use								

Location	Science E-3 - 6	Science E-3 - 8	Science E-3 - 9	Science - E-3 Eye	Science - E-3B	Science - E-4 - 2	Science - E-4 - 3	Science - E-4 - 4
Test results	32.7	90.4	89.6	58.9	245	111	78.1	32.9
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Back in use								

Location	Science - E-4 - 5	Science - E-4 - 7	Science - E-4 - 8	Science - E-4 - Eye	Science - E-5 -1	Science - E-5 -2	Science - E-5 -3	Science - E-5 - 4
Test results	53	64.1	65.2	18.4	21.1	27.3	26	23.4
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Back in use								

Location	Science - E-5 B sink	Science E-7 - 2	Science E-7 - Eye	Science E-7 - Shower	Science EB-sink	Science E8 - 2
Test results	159	26	39.9	31.2	22.5	19.7
Remediation	Signage	Signage	Signage	Signage	Signage	Signage
Back in use						

AIM building

Location
Test results

District office

Location
Test results