

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occuring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Country Parkway	District has received all first round water sampling results							
Location	Rm 119, fountain	Rm 121, fountain	Rm 125, fountain	Staff kitchen lav	IMC, hose bib	Custodial closet #2	Outdoor -Boiler rm	Outdoor-by 122
Results	16.70	17.30	20.20	27.30	13400.00	39.00	131.00	232.00
Remediation	Replaced fountain	Replaced fountain	Replaced fountain	Sign-nondrinking	Sign-nondrinking	Sign-nondrinking	Sign-nondrinking	Sign-nondrinking
Results	Pending	13.2	Pending					
Back in use		11/1/2016						
Location	Outdoor-by115	Outdoor-by108	Outdoor-by 105	Outdoor-by100	Outdoor-by-Office	Girls LR shower	Boys-LR shower	Custodial by rm 100
Results	59.10	135.00	223.00	139.00	198.00	53.90	16.70	27.20
Remediation	Sign-nondrinking	Sign-nondrinking	Sign-nondrinking	Sign-nondrinking	Sign-nondrinking			Sign-nondrinking
Results								
Back in use								
Location	Library office sink	Rm 104, sink	Rm 104, fountain	Rm 106, sink	Rm 106, fountain	Rm 107, sink	Rm 108, sink	Rm 110, sink
Results	17.00	39.30	457.00	20.30	17.60	21.10	26.30	15.90
Remediation								
Results								
Back in use								
Location	Rm 117, sink	Rm 117, fountain	Rm 118, sink	Rm 118, fountain	Speech office sink	Outdoor-by-120	Outdoor-by-106	
Results	18.10	23.70	22.10	27.00	18.30	77.30	30.20	
Remediation						Sign-nondrinking	Sign-nondrinking	
Results								
Back in use								

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occuring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Dodge	d water sampling results							
Location	Rm 106, bathroom	Rm 108, bathroom	Rm 107, bathroom	Rm 109, bathroom	Boys LR, coach sink	Custodial outlet 120	Rm 144, class sink	Boiler room
Results	23.10	39.90	28.80	28.60	30.50	24.60	22.10	33.00
Remediation								
Results								
Back in use								
Location	Girl's coach sink	Girl's coach shower	Outdoor-by 137	Outdoor-by-143	Outdoor-by-130			
Results	16.60	535.00	214.00	557.00	18.50			
Remediation								
Results								
Back in use								
Forest	d water sampling results							
Location	Rm 20, sink #3	Rm 18, sink	Rm 1, sink	Rm 38, sink	Rm 36, sink	Rm 39, sink	Boys coach office	Staff kitchen lav
Test results	36.10	17.80	18.20	17.30	20.00	21.40	19.90	18.00
Remediation	Replace fixture	Replace fixture	Replace fixture		Replace fixture	Replace fixture		
Results	13.50	4.71	12.70		Pending	12.40		
Back in use	11/1/2016	11/1/2016	11/1/2016			11/1/2016		
Back in use								
Location	Kitchen sink-west	Kitchen sink-dish	Outdoor-by rm 16	Outdoor-by rm 1	Outdoor-by rm 2			
Test results	15.40	26.00	30.10	95.10	184.00			
Remediation								
Results								
Back in use								

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occuring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Heim	<u>d water sampling results</u>							
Location	Rm 109, sink	Rm 112	Staff kitchen lav	Custodial shower	Outdoor-courtyard	Outdoor-by 147	Outdoor-by 106	Outdoor-by office
Test results	15.60	687.00	15.40	53.30	17.00	45.20	95.80	73.40
Remediation								
Results								
Back in use								
Location	Outdoor-by generator	Kitchen-custodial	Outdoor-by 132	Outdoor-by-142	Rm 188, music			
Test results	61.30	1390.00	122.00	1210.00	21.20			
Remediation								
Results								
Back in use								
Maple East	<u>d water sampling results</u>							
Location	Rm 39, sink	Rm 39, fountain	Rm 29, sink #3	Outdoor-courtyard	Library office sink	Rm 67. sink	Rm 56c, sink	Outdoor-by-Main
Test results	27.00	24.80	932.00	117.00	32.40	240.00	27.40	36.20
Remediation								
Results								
Back in use								
Location	Outdoor-by-20	Boiler rm eyewash	Rm 56-c Sink	Rm 49, girls shower	Rm 46, sink	Rm 46, fountain		
Test results	98.50	75.20	41.10	58.80	15.90	24.50		
Remediation								
Results								
Back in use								

12/8/2016

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Maple West								
<u>d water sampling results</u>								
Location	Custodial by gym	Custodial-Bathroom	Custodial-shower	Custodial-by-Kitchen	Outdoor-by-124	Outdoor-by dock	Kitchen - cleaning	Rm 7, sink
Test results	20.90	20.60	138.00	30.30	41.10	255.00	82.40	38.40
Remediation	Second test				Second test			
Results	9.65				85.90			
Back in use								
Location	Rm 113, sink #1	Library office sink	Athletic -girls shower	Athletic-boys-shower	Boiler rm eyewash	Outside-by-main	Outside-by-129	Hallway fountain-2
Test results	17.10	19.60	174.00	60.00	81.20	30.70	91.10	18.00
Remediation								
Results								
Back in use								
Casey middle								
Location								
Test results								
Location								
Test results								
Heim middle								
Location								
Test results								
Location								
Test results								

12/8/2016

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Mill middle								
Location	Custodial sink M-4	Girl's LR shower #1	Girl's LR shower #2	Girl's LR shower #3	Girl's LR shower #4	Girl's LR shower #8	Girl's LR shower #9	Girl's LR shower #10
Test results	15.2	41.3	38.3	35.9	22.7	63.6	43.3	65.6
Remediation	signage	signage	signage	signage	signage	signage	signage	signage
Back-in service								
Location	Girl's LR shower #11	Girl's LR shower #12	Girl's LR shower #13	Girl's LR shower #14	Girl's LR shower #15	Girl's LR shower #16	Kitchen dish sprayhead	Pool filter faucet
Test results	35.6	26.4	28.8	28.9	25.8	32.8	21.6	35.9
	signage	signage	signage	signage	signage	signage	signage	signage
Location	Loading dock Faucet							
Test results	18.9							
	signage							
Transit middle								
Location								
Test results								
Location								
Test results								

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

East high								
Location	Science- 241 -sink 1	Science-223-sink 4	Science-223-sink 5	Science-219-sink 1	Science- 222-sink 2	Science-222-sink 5	Science-222-sink6	Science-222 sink 7
Test results	29.8	37.9	19.4	29.8	32.9	22.7	47	31.4
Remediation	signage	signage	signage	signage	signage	signage	signage	signage
Back-in-service								
Location	Science-222A	Girl's Lav-Green Sink 1	IMC sink	Boy's coaches shower	Boys locker rm sink#1	Boys Shower #1	Girls locker rm sink#1	Girls shower #1
Test results	21.4	174	552	33.1	21.9	42.7	21.2	368
Remediation	signage							
Back-in-service								
Location	Fitness room fountain	3rd Fl Men's Lav sink	3rd Fl Girl's lav	Science-222-sink 4				
Test results	51.9	61.9	4780	29.9				
Remediation				signage				
Back-in-service								

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

North high								
Location	Custodial basement #1	Basement storeroom	Hall fountain A-146	Career Center #1	Career Center #2	Science A-113 #2	Science A-120 #9	Science A119 #5
Test results	57.3	138	20.1	40.5	55.2	26	85.1	19.2
Remediation	Signage	Signage	New fountain	Change faucet	Change faucet	Signage	Signage	Signage
Back-in-service			No down time					
Location	Science A-119 #7	Science A-119 # 8	Science A-119 #9	Hall Fountain A-120				
Test results	19.6	15.2	22.9	83.8				
Remediation	Signage	Signage	Signage	New fountain				
Back-in-service				No down time				

12/8/2016

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

<u>South high</u>								
Location	Boiler room	Science E-1	Science E-2B	Mens lav - E-2 #2	Science E-3 - 2	Science E-3 - 3	Science E-3 - 4	Science E-3 - 5
Test results	29.9	18.8	41.3	28.9	115	57.7	38	37.2
Remediation	Signage	Signage	Signage		Signage	Signage	Signage	Signage
Results								
Back in use								
Location	Science E-3 - 6	Science E-3 - 8	Science E-3 - 9	Science - E-3 Eye	Science - E-3B	Science - E-4 - 2	Science - E-4 - 3	Science - E-4 - 4
Test results	32.7	90.4	89.6	58.9	245	111	78.1	32.9
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Back in use								
Location	Science - E-4 - 5	Science - E-4 - 7	Science - E-4 - 8	Science - E-4 - Eye	Science - E-5 -1	Science - E-5 -2	Science - E-5 -3	Science - E-5 - 4
Test results	53	64.1	65.2	18.4	21.1	27.3	26	23.4
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Back in use								
Location	Science - E-5 B sink	Science E-7 - 2	Science E-7 - Eye	Science E-7 - Shower	Science EB-sink	Science E8 - 2		
Test results	159	26	39.9	31.2	22.5	19.7		
Remediation	Signage	Signage	Signage	Signage	Signage	Signage		
Back in use								
<u>AIM building</u>								
Location								
Test results								
<u>District office</u>								
Location								
Test results								