

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Mill middle

Location	Custodial sink M-4	Girl's LR shower #1	Girl's LR shower #2	Girl's LR shower #3	Girl's LR shower #4	Girl's LR shower #8	Girl's LR shower #9	Girl's LR shower #10
Test results	15.2	41.3	38.3	35.9	22.7	63.6	43.3	65.6
Remediation	signage	signage	signage	signage	signage	signage	signage	signage
Back-in service								

Location	Girl's LR shower #11	Girl's LR shower #12	Girl's LR shower #13	Girl's LR shower #14	Girl's LR shower #15	Girl's LR shower #16	Kitchen dish sprayhead	Pool filter faucet
Test results	35.6	26.4	28.8	28.9	25.8	32.8	21.6	35.9
Remediation	signage	signage	signage	signage	signage	signage	signage	signage

Location	Loading dock Faucet
Test results	18.9
Remediation	signage

Transit middle

Location	Science - A110 - #1	Library office sink	Outside faucet A105
Test results	19.7	24	87
Remediation			

Location	
Test results	
Remediation	

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

North high

Location	Custodial basement #1	Basement storeroom	Hall fountain A-146	Career Center #1	Career Center #2	Science A-113 #2	Science A-120 #9	Science A119 #5
Test results	57.3	138	20.1	40.5	55.2	26	85.1	19.2
Remediation	Signage	Signage	New fountain	Change faucet	Change faucet	Signage	Signage	Signage
Back-in-service			No down time					

Location	Science A-119 #7	Science A-119 # 8	Science A-119 #9	Hall Fountain A-120
Test results	19.6	15.2	22.9	83.8
Remediation	Signage	Signage	Signage	New fountain
Back-in-service				No down time

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

South high

Location	Boiler room	Science E-1	Science E-2B	Mens lav - E-2 #2	Science E-3 - 2	Science E-3 - 3	Science E-3 - 4	Science E-3 - 5
Test results	29.9	18.8	41.3	28.9	115	57.7	38	37.2
Remediation	Signage	Signage	Signage		Signage	Signage	Signage	Signage
Results								
Back in use								

Location	Science E-3 - 6	Science E-3 - 8	Science E-3 - 9	Science - E-3 Eye	Science - E-3B	Science - E-4 - 2	Science - E-4 - 3	Science - E-4 - 4
Test results	32.7	90.4	89.6	58.9	245	111	78.1	32.9
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Back in use								

Location	Science - E-4 - 5	Science - E-4 - 7	Science - E-4 - 8	Science - E-4 - Eye	Science - E-5 -1	Science - E-5 -2	Science - E-5 -3	Science - E-5 - 4
Test results	53	64.1	65.2	18.4	21.1	27.3	26	23.4
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage

Location	Science - E-5 B sink	Science E-7 - 2	Science E-7 - Eye	Science E-7 - Shower	Science EB-sink	Science E8 - 2
Test results	159	26	39.9	31.2	22.5	19.7
Remediation	Signage	Signage	Signage	Signage	Signage	Signage
Back in use						

AIM building

Location
Test results

District office

Location
Test results