

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occuring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Country Parkway								
Location	Rm 119, fountain	Rm 121, fountain	Rm 125, fountain	Staff kitchen lav	IMC, hose bib	Custodial closet #2	Outdoor -Boiler rm	Outdoor-by 122
Results	16.70	17.30	20.20	27.30	13400.00	39.00	131.00	232.00
Remediation	Replaced fountain	Replaced fountain	Replaced fountain	New faucet	Signage	Signage	Signage	Signage
Results	27.6	13.2	20.1	Pending	NA	NA	NA	NA
Results	20.5	NA	15.9	31.6	NA	NA	NA	NA
Results	NA	NA	10.8	NA	NA	NA	NA	NA
Back in use	TBD	11/1/2016	3/17/17	TBD	12/6/16	10/24/16	12/6/16	12/6/16
Location	Outdoor-by115	Outdoor-by108	Outdoor-by 105	Outdoor-by100	Outdoor-by-Office	Girls LR shower	Boys-LR shower	Custodial by rm 100
Results	59.10	135.00	223.00	139.00	198.00	53.90	16.70	27.20
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Results	NA	NA	NA	NA	NA	NA	NA	NA
Back in use	12/6/16	12/6/16	12/6/16	12/6/16	12/6/16	12/6/16	12/6/16	12/6/16
Location	Library office sink	Rm 104, sink	Rm 104, fountain	Rm 106, sink	Rm 106, fountain	Rm 107, sink	Rm 108, sink	Rm 110, sink
Results	17.00	39.30	457.00	20.30	17.60	21.10	26.30	15.90
Remediation	New faucet	New faucet	New fountain	New faucet	New faucet	New faucet	New faucet	New faucet
Results	12.90	12.70	Pending	11.60	16.10	12.20	25.90	20.66
Results	NA	NA	33.20	NA	12.70	NA	17.00	20.60
Results	NA	NA		NA	NA	NA	12.60	NA
Back in use	12/16/16	2/9/17	TBD	2/9/17	3/17/17	12/16/16	3/17/17	TBD
Location	Rm 117, sink	Rm 117, fountain	Rm 118, sink	Rm 118, fountain	Speech office sink	Outdoor-by-120	Outdoor-by-106	Rm 162 , fountain
Results	18.10	23.70	22.10	27.00	18.30	77.30	30.20	20.50
Remediation	New faucet	New fountain	New faucet	New fountain	New faucet	Signage	Signage	Replaced fountain
Results	12.70	Pending	14.00	Pending	12.30	NA	NA	TBD
Results 2	NA	18.30	NA	15.70	NA	NA	NA	
Back in use	2/9/17	TBD	2/9/17	TBD	12/16/16	12/6/16	12/6/16	TBD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occuring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Dodge								
Location	Rm 106, bathroom	Rm 108, bathroom	Rm 107, bathroom	Rm 109, bathroom	Boys LR, coach sink	Custodial outlet 120	Rm 144, class sink	Boiler room
Results	23.10	39.90	28.80	28.60	30.50	24.60	22.10	33.00
Remediation	New faucet	New faucet	New faucet	New faucet	Install pending	Signage	New faucet	Flushing process
Results	3.74	3.17	10.40	4.15	5.82	NA	2.31	4.45
Back in use	2/9/17	2/9/17	2/9/17	2/9/17	3/16/17	12/1/16	2/9/17	3/17/17
Location	Girl's coach sink	Girl's coach shower	Outdoor-by 137	Outdoor-by-143	Outdoor-by-130			
Results	16.60	535.00	214.00	557.00	18.50			
Remediation	Install pending	Signage	Signage	Signage	Signage			
Results	2.76	NA	NA	NA	NA			
Back in use	3/17/2017	12/1/16	12/1/16	12/1/16	12/1/16			
Forest								
Location	Rm 20, sink #3	Rm 18, sink	Rm 1, sink	Rm 38, sink	Rm 36, sink	Rm 39, sink	Boys coach office	Staff kitchen lav
Test results	36.10	17.80	18.20	17.30	20.00	21.40	19.90	18.00
Remediation	Replace fixture	Replace fixture	Replace fixture	Pending	Replace fixture, stops	Replace fixture	Replace fixture	New faucet
Results	13.50	4.71	12.70	Pending	15.30	12.40	Pending	5.64
Results	NA	NA	NA	NA	46.60	NA		NA
Results	NA	NA	NA	NA	13.10	NA		NA
Back in use	11/1/2016	11/1/2016	11/1/2016	TBD	3/17/17	11/1/2016	TBD	2/9/17
Location	Kitchen sink-west	Kitchen sink-dish	Outdoor-by rm 16	Outdoor-by rm 1	Outdoor-by rm 2			
Test results	15.40	26.00	30.10	95.10	184.00			
Remediation	Replace fixture	Replace fixture	Signage	Signage	Signage			
Results	6.28	6.28	NA	NA	NA			
Back in use	3/17/17	3/17/17	11/2/2016	11/2/2016	11/2/2016			

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occuring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Heim								
Location	Rm 109, sink	Rm 112	Staff kitchen lav	Custodial shower	Outdoor-courtyard	Outdoor-by 147	Outdoor-by 106	Outdoor-by office
Test results	15.60	687.00	15.40	53.30	17.00	45.20	95.80	73.40
Remediation	New faucet	Removed	New faucet	Signage	Signage	Signage	Signage	Signage
Results	45.60	NA	21.80	NA	NA	NA	NA	NA
Results 2	5.95	NA	24.40	NA	NA	NA	NA	NA
Back in use	3/17/17	NA	TBD	12/6/16	12/6/16	12/6/16	12/6/16	12/6/16
Location	Outdoor-by generator	Kitchen-custodial	Outdoor-by 132	Outdoor-by-142	Rm 188, music			
Test results	61.30	1390.00	122.00	1210.00	21.20			
Remediation	Signage	Removed	Signage	Signage	New faucet			
Results	NA	NA	NA	NA	17.50			
Results	NA	NA	NA	NA	586.00			
Results	NA	NA	NA	NA	13.60			
Back in use	12/6/16	NA	12/6/16	12/6/16	3/17/17			
Maple East								
Location	Rm 39, sink	Rm 39, fountain	Rm 29, sink #3	Outdoor-courtyard	Library office sink	Rm 67. sink	Rm 56c, sink	Outdoor-by-Main
Test results	27.00	24.80	932.00	117.00	32.40	240.00	27.40	36.20
Remediation	New faucet	New fountain	Pending	Signage	New faucet	New faucet	New faucet	Signage
Results	8.48	10.90	Pending	NA	1.96	0.00	6.37	NA
Back in use	2/9/17	2/9/17	TBD	12/2/16	2/9/17	2/9/17	3/17/17	12/2/16
Location	Outdoor-by-20	Boiler rm eyewash	Rm 56-c Sink	Rm 49, girls shower	Rm 46, sink	Rm 46, fountain		
Test results	98.50	75.20	41.10	58.80	15.90	24.50		
Remediation	Signage	Signage	New faucet	New faucet	New faucet	New fountain		
Results	NA	NA	6.37	20.90	1.41	4.98		
Results	NA	NA	NA	11.50	NA	NA		
Back in use	12/2/2016	12/2/2016	2/9/17	3/17/17	2/9/17	2/9/2017		

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occuring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Maple West								
Location	Custodial by gym	Custodial-Bathroom	Custodial-shower	Custodial-by-Kitchen	Outdoor-by-124	Outdoor-by dock	Kitchen - cleaning	Rm 7, sink
Test results	20.90	20.60	138.00	30.30	41.10	255.00	82.40	38.40
Remediation	Signage	New faucet	Signage	Signage	Signage	Signage	New faucet	New faucet
Results	NA	17.80	NA	NA	NA	NA	85.90	9.70
Test results	NA	74.80	NA	NA	NA	NA	6.20	NA
Back in use	12/2/16	TBD	12/2/16	12/2/16	12/2/16	12/2/16	2/9/17	12/16/16
Location	Rm 113, sink #1	Library office sink	Athletic -girls shower	Athletic-boys-shower	Boiler rm eyewash	Outside-by-main	Outside-by-109	Hallway fountain-2
Test results	17.10	19.60	174.00	60.00	81.20	30.70	91.10	18.00
Remediation	New faucet	New faucet	Signage	New faucet	Signage	Signage	Signage	Pending
Results	11.50	17.30	NA	<1.0	NA	NA	NA	Pending
Results	NA	10.40	NA	NA	NA	NA	NA	
Back in use	12/16/16	3/17/17	12/2/16	12/16/16	12/2/16	12/2/16	12/2/16	TBD
Casey middle								
Location	Stage sink	Room 135 #3	Room 135 #4	Room 139 #1	Room 139A	Faculty lav sink 2	Girl's LR shower #2	Girl's LR shower #5
Test results	76.5	27.2	41.8	30.5	22.6	31.6	40.1	21.9
Test results	New faucet	Signage	Signage	Signage	Signage	9.74	NA	NA
Remediation	NA	NA	NA	NA	NA	change faucet	Signage	Signage
Back in use	TBD	In use	In use	In use	In use	3/17/17	In use	In use
Location	Girl's LR shower #6	Kitchen lav sink	Custodial Mech	Outside faucet - 131	Outside hose bib 140	Outside hose bib 144	Hose bib pool rm	Eye wash pool rm
Test results	16.9	17.8	52.7	24.6	27.7	605	44.8	85.9
Remediation	Signage	change faucet/sign	Signage	Signage	Signage	Signage	Signage	Signage
Results	NA	5.84	NA	NA	NA	NA	NA	NA
Back in use	In use	In use	In use	In use	In use	In use	In use	In use
Location	Science eye wash -215	Science rm 216 sink-4	Science eye wash-216	Science rm217 sink 1	Science rm217 sink 3	Science rm217 sink 4	Science eye wash-217	Science rm114 sink
Test results	39.6	46.1	17.7	22.3	19.4	34.5	15.1	24.4
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Back in use	In use	In use	In use	In use	In use	In use	In use	In use
Location	Boys LR shower #5	Tech rm 130 sink						
Test results	16.1	18.4						
Remediation	Signage	Signage						
Back in use	In use	In use						

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occuring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Heim middle								
Location	Hec- outlet for washer	Science-B-14-#2	Science-B-14-#3	Science-C-11 #3	Science-C-11 #2	Science-C-13 #4	Sciecne D10 - sink 1	Science D10 sink 2
Test results	32.7	15.3	17.4	71.9	18.1	25.8	323	20
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Back in svc.	In use	In use	In use	In use	In use	In use	In use	In use
Location	Science D10 sink 3	Science D10 sink 4	Science D10 sink 5	Science D10 sink 6	Science D10 sink 9	Science D8 sink 1	Science D8 sink2	Science D7 sink1
Test results	867	124	65.4	1050	449	52.3	245	27.5
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Back in svc.	In use	In use	In use	In use	In use	In use	In use	In use
Location	Science D7 sink 4	D7 washing machine	Tech D6 sink 1	Tech D6 sink 2	Boys LR sink 2	Gym fountain	Girls LR shower 8	A-13 sink 1
Test results	20	30.5	41.8	87.6	17.4	44	34.6	44.3
Remediation	Signage	Signage	Signage	Signage	Signage	Replacement	Signage	Faucet replacement
Results	NA	NA	NA	NA	3.21		NA	
Back in svc.	In use	In use	In use	In use	3/17/17	TBD	In use	TBD
Location	Men's Lav by Aud sink 1	Custodial sink kitchen	Facility fan room	Hose bib pool	Hose bib outside	Hose bib courtyard A	Hose bib courtyard B	Hose bib courtyard C
Test results	19.70	20.30	132.00	26.40	31.60	62.7	2310.00	5880
Remediation	Faucet replacement	Faucet replacement	Signage	Signage	Signage	Signage	Signage	Signage
Results	3.97		NA	NA	NA	NA	NA	NA
Back in svc.	3/17/17	TBD	In use	In use	In use	In use	In use	In use
Location	Boiler rm eye wash	Outside hose bib D10	Outside hose bib aud	Outside hose bib C-11	Outside hose bib C-2	Outside hose bib B-11	Outside hose bib B-2	Outside hose bib A-10
Test results	57.20	36.20	112.00	119.00	93.70	46.3	62.00	156
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Back in svc.	In use	In use	In use	In use	In use	In use	In use	In use
Location	Outside hose bib A-2	Outside hose bib flag						
Test results	193.00	299.00						
Remediation	Signage	Signage						
Back in svc.	In use	In use						

3/20/2017

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

[illegible]

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occuring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Mill middle								
Location	Classroom A-8 sink	Classroom A-9 sink	Classroom A-11 sink	Classroom A-10 sink	Classroom A-13 sink	Library office sink	Boy's Lav by A-11	Custodial by library
Test results	39.4	59.2	27.5	26	33.7	21.9	20.2	60.3
Remediation	TBD	Replace faucet	Replace faucet	Replace faucet	Replace faucet	Replace faucet	Replace faucet	signage
Test results		21.6	13.7	40.9	6.96	11.3	signage	NA
Back in svc.	TBD	TBD	2/9/2017	TBD	2/9/2017	3/16/2017	In use	In use
Location	Science B-2 sink1	Science B-2 sink2	Science B-2 sink3	Science B2 Tchr office 1	Science B2 Tchr office 2	Science B-4 sink1	Science B-4 sink2	Science B-4 sink3
Test results	40.3	71.6	69.2	73.8	57.6	33.5	17.7	70.9
Remediation	signage	signage	signage	signage	signage	signage	signage	signage
Back in svc.	In use	In use	In use	In use	In use	In use	In use	In use
Location	Classroom B-6 sink	Classroom B-8 sink	Science B-9 sink	Classroom B-11 sink	Classroom B-10 sink	Classroom B-13 sink	IMC sink	Hose bib boiler rm
Test results	19.7	18.5	21.7	36.3	32.8	32.3	16	63.1
Remediation	Replace faucet	Replace faucet	Replace faucet	Replace faucet	Replace faucet	TBD	Replace faucet	signage
Test results	14.7	87.9	8.21	16	20		3.18	NA
Test results	NA		NA	13.6			NA	NA
Back in svc.	2/9/2017	TBD	2/9/2017	3/16/2017	TBD	TBD	3/16/2017	In use
Location	Hose bib pool mech rm	Science B-4 sink4						
Test results	70.3	27						
Remediation	signage	signage						
Back in svc.	In use	In use						

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occuring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Transit middle								
Location	Science - A110 - #1	Library office sink	Outside faucet A105	Boy's LR shower 1	Boy's LR shower 2	Boy's LR shower 6	Boy's LR shower 7	Boy's LR shower 8
Test results	19.7	24	87	63.6	22.6	29.2	67.2	16
Test results	NA	7.44	NA	NA	NA	NA	NA	NA
Remediation	Signage	Change faucet	Signage	Signage	Signage	Signage	Signage	Signage
Back in svc.	In use	In use	In use	In use	In use	In use	In use	In use
Location	Boy's LR shower 9	Girl's coach shower	Girl's LR shower 2	Girl's LR shower 3	Girl's LR shower 4	Girl's LR shower 9	Pool chem eyewash	Pool chem hose faucet
Test results	15.7	68.1	19.9	43.2	66.2	45.8	39.8	17
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Back in svc.	In use	In use	In use	In use	In use	In use	In use	In use
Location	Pool deck faucet 1	Pool deck faucet 2	Tech rm 108 - #4	Tech rm 108 - #6	Tech rm 108 - #7	Science B123-2	Science B123 - 3	Science B229 sink 1
Test results	83	24.4	21.3	158	16.6	80.7	32.5	15.6
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Back in svc.	In use	In use	In use	In use	In use	In use	In use	In use
Location	Science B229 sink 4	Science B229 sink 5	Science B229 sink 6	Science B229 sink 8	Science B229 sink 9	Science B229 sink 10	Science B229 sink 11	Science B229 sink 12
Test results	21	28.8	16.9	19.2	24.4	39.6	16.8	27.8
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Back in svc.	In use	In use	In use	In use	In use	In use	In use	In use
Location	Science B229 eyewash	Science B227 sink 1	Science B212 sink 1	Science B212 sink 2	Science B212 sink 3	Science B214 sink 2	Science B214 sink 3	Science B214 sink 4
Test results	442	2490	27.1	16	23	221	37.6	82.3
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Back in svc.	In use	In use	In use	In use	In use	In use	In use	In use
Location	Science B214 sink 5	Science B214 sink 6	Science B214 sink 7	Science B214 sink 8	Science B214 sink 9	Science B214 sink 10	Custodial sink by 214	Room A214 tcher sink
Test results	44.5	53.9	23.2	41.8	35.5	25.6	52.4	39.3
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage
Back in svc.	In use	In use	In use	In use	In use	In use	In use	In use
Location	Outside hose bib B123	Outside hose bib A105						
Test results	37.1	87						
Remediation	Signage	Signage						
Back in svc.	In use	In use						

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

[illegible]

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

East high								
Location	Girl's LR shower 2	Girl's LR shower 3	Girl's LR shower 4	Girl's LR shower 5	Girl's LR shower 6	Girl's LR shower 7	Girl's LR shower 8	Girl's LR shower 9
Test results	68.9	1970	85.2	73	186	101	154	58.4
Remediation	signage	signage	signage	signage	signage	signage	signage	signage
Back in svc.	In use	In use	In use	In use	In use	In use	In use	In use
Location	Girl's LR shower 10	Girl's LR shower 11	Boy's LR shower 1	Boy's LR shower 2	Boy's LR shower 3	Boy's LR shower 4	Boy's LR shower 5	Boy's LR shower 6
Test results	62.6	167	30.3	48.4	76.3	40.5	15.1	21.1
Remediation	signage	signage	signage	signage	signage	signage	signage	signage
Back in svc.	In use	In use	In use	In use	In use	In use	In use	In use
Location	Boy's LR shower 7	Boy's LR shower 8	Boy's LR shower 9	Boy's LR shower 10	Boy's LR shower 11	Boy's Team 1 rm shw 4	Boy's Team rm 1 shw 5	Boy's Team rm 1 shw 6
Test results	120	75.6	65.8	53.3	47.2	62.6	24.6	17.1
Remediation	signage	signage	signage	signage	signage	signage	signage	signage
Back in svc.	In use	In use	In use	In use	In use	In use	In use	In use
Location	Boy's Team rm 2 sh 3	Boy's Team rm 2 shw 4	Boy's Team rm 2 shw 5	Boy's Team rm 2 shw 6	Custodial Team rm 2 bib	Custodial 2nd fl. Lav bib	Custodial 2nd fl. Lav bib	Custodial 2nd fl. Lav bib
Test results	25.8	43.1	33.6	25.7	137	385	452	1390
Remediation	signage	signage	signage	signage	signage	signage	signage	signage
Back in svc.	In use	In use	In use	In use	In use	In use	In use	In use
Location	Custodial 2nd fl. Lav bib	Science rm 225 sink 1	Science rm 225 sink2	Science rm 225 sink 3	Science rm 225 sink 4	Science rm 225 sink 5	Science rm 224 sink 2	Kitchen sink 10
Test results	79.6	19.5	36.8	31.9	55.4	51.4	43.1	21.2
Test results	NA	NA	NA	NA	NA	NA	NA	12.4
Remediation	signage	signage	signage	signage	signage	signage	signage	signage/change faucet
Back in svc.	In use	In use	In use	In use	In use	In use	In use	In use
Location	Kitchen pot sink 1	Kitchen pot sink 2	Custodial girl lav bib	Custodial boy lav bib	Photo lab sink 7	Photo lab sink 8	Boy's LR hose bib	Boy's coach office
Test results	26.7	16.7	86.6	232	74.1	51.7	145	17.7
Test results	7.31	6.9	signage/change faucet	signage/change faucet	signage/change faucet	signage/change faucet	signage/change faucet	3.57
Remediation	signage/change faucet	signage/change faucet	signage	signage	signage	signage	signage	signage/change faucet
Back in svc.	In use	In use	In use	In use	In use	In use	In use	In use
Location	Boy's Team rm 1 bib							
Test results	105							
Remediation	signage							
Back in svc.	In use							

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

[illegible]

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

[illegible]

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occuring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

South high									
Location	Old gym SR shower9	Old gym SR shower10	Old gym SR shower11	Old gym SR shower12	Tech room 129 sink 1	Tech room 129 sink 3	Tech room 129 sink 4	Girl's coach shower	
Test results	382	67	68.1	328	134	43	183	31.2	
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage	
Back in use	In use	In use	In use	In use	In use	In use	In use	In use	
Location	SR custodial hose bib	Old gym fountain	Boy's lav hose bib 107	Girl's LR hose bib	Basement custodial	New gym BoyLR shwr 2	New gym BoyLR shwr 3	New gym BoyLR shwr 4	
Test results	20.7	37.5	766	149	111	62.7	112	188	
Remediation	Signage	Replacement	Signage	Signage	Signage	Signage	Signage	Signage	
Back in use	In use	TBD	In use	In use	In use	In use	In use	In use	
Location	New gym BoyLR shwr 5	New gym BoyLR shwr 6	New gym BoyLR shwr 7	New gym BoyLR shwr 8	New gym BoyLR shwr 9	Boy's coach office NG shw	Custodial sink by 142	New gym GirlLR shwr1	
Test results	18.5	123	89.3	115	23.6	27	18.8	444	
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage	
Back in service	In use	In use	In use	In use	In use	In use	In use	In use	
Location	New gym GirlLR shwr2	New gym GirlLR shwr3	New gym GirlLR shwr4	Science E-8 #6	Science E-8- shower	Science E-8 Vacuum sink	Science E-10 Eye Wash	Science E-9 Eye Wash	
Test results	426	5110	1180	17.2	46	48.5	33.2	37.1	
Remediation	Signage	Storage area-sign	Storage area-sign	Signage	Signage	Signage	Signage	Signage	
Back in use	In use	In use	In use	In use	In use	In use	In use	In use	
Location	Science E-14 Eye Wash	Girls squad shower1	Girls squad shower 2	Girls squad shower 3	Girls squad shower 4	Girls squad shower 5	Girls squad shower 6	Girls squad shower 7	
Test results	25.1	1050	4240	3530	4640	1960	235	1670	
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage	
Back in service	In use	In use	In use	In use	In use	In use	In use	In use	
Location	Girls squad shower 8	Girls squad shower 9	Girls squad shower 10	Girls squad shower 11	Girls squad shower 12	Girls squad shower 13	Girls LR shower 1	Girls LR shower 2	
Test results	12200	418	930	379	1120	150	153	130	
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage	
Back in use	In use	In use	In use	In use	In use	In use	In use	In use	
Location	Girls LR shower 3	Girls LR shower 4	Girls LR shower 5	Girls LR shower 6	Girls LR shower 7	Boys LR shower 2	New gym Girls shower 5	New gym Girls shower 6	
Test results	296	537	216	190	130	25.8	469	600	
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage	Signage	
Back in use	In use	In use	In use	In use	In use	In use	In use	In use	

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occuring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

South high									
Location	New gym Girls shower 7	New gym Girls shower 8	New gym coach shwr	New Gym Boy Lav sink	Science 134 sink #2	Bathroom by 132 sink1	Bathroom by 132 sink2	Custodial by 204	
Test results	352	617	492	18	17.3	16.6	48.6		22.8
Remediation	Signage	Signage	Signage	Replace faucet	Signage	Replace faucet	Replace faucet		Signage
Back in use	In use	In use	In use	TBD	In use	3/16/2017	3/16/2017		In use
Location	Classroom sink 235	Custodial by 219	Outside hose-Science	Outside hose					
Test results	19.7	16.2	18.8	22					
Remediation	Replace faucet	Signage	Signage	Signage					
Back in use	TBD	In use	In use	In use					
AIM building									
Location	Science - 1	Science - 2	Science - 4	Science - 5	Sceince eyewash	Outside faucet-013	Outside faucet - 10		
Test results	20.4	31.3	86.4	60.2	26.3	31.5	132		
Remediation	Signage	Signage	Signage	Signage	Signage	Signage	Signage		
Back in use	In use	In use	In use	In use	In use	In use	In use		
District office									
Location									
Test results									

Hose bib: A hose bib is a faucet that is used to connect a hose for cleaning purposes. These faucets are not meant for use as a source of drinking water.