

Williamsville Central School District
 New York State Public School District
 Water Testing for Lead (Final Report)

6/19/2017

School	Number of Samples Tested (1)	Number of Samples Not Addressed	Location of Samples Tested above 15ppb (2)										Received All Results Yes - No	
			Hallway Drinking Fountains	Student Lavatories	Classroom Faucets	Classroom Fountains	Student-staff Showers/ Locker rooms	Office Sinks	Staff Lavatories	Custodial Outlets	Child Nutrition Faucets	Outdoor Faucets		
Country Parkway	135	0	0	0	0	0	0	0	0	0	0	0	0	Yes
Dodge	111	0	0	0	0	0	0	0	0	0	0	0	0	Yes
Forest	140	0	0	0	0	0	0	0	0	0	0	0	0	Yes
Heim	127	0	0	0	0	0	0	0	0	0	0	0	0	Yes
Maple East	143	0	0	0	0	0	0	0	0	0	0	0	0	Yes
Maple West	137	0	0	0	0	0	0	0	0	0	0	0	0	Yes
Casey middle	156	0	0	0	0	0	0	0	0	0	0	0	0	Yes
Heim middle	206	0	0	0	0	0	0	0	0	0	0	0	0	Yes
Mill middle	202	0	0	0	0	0	0	0	0	0	0	0	0	Yes
Transit middle	182	0	0	0	0	0	0	0	0	0	0	0	0	Yes
East high	272	0	0	0	0	0	0	0	0	0	0	0	0	Yes
North high	310	0	0	0	0	0	0	0	0	0	0	0	0	Yes
South high	297	0	0	0	0	0	0	0	0	0	0	0	0	Yes
AIM building	20	0	0	0	0	0	0	0	0	0	0	0	0	Yes
District office	21	0	0	0	0	0	0	0	0	0	0	0	0	Yes
Total Samples	2459	0	0	0	0	0	0	0	0	0	0	0	0	
													0	

(1) New York State water testing parameters for lead require all water outlets to be tested after water has been stagnant in the water pipes and faucets for a minimum of eight hours. Flushing water through the water outlet is not permitted per the test.

(2) A failed test results in immediate remediation efforts by the District. The water supply is turned off and the most common repair is to replace the fixture and retest the water from the location.