

LOCATION	OBSERVATION	RECOMMENDATIONS
9 Lafayette Avenue	24" tree with roots against curb	Tree root protection plate to be installed
11 Lafayette Avenue	28" Sweetgum (F1) is in good condition and overhangs part of the curb and road	Tree to be removed due to construction
15 Lafayette Avenue	36" Sweetgum (F1) is in good condition and overhangs part of the curb and road	Tree to be removed due to construction
17 Lafayette Avenue	40" London Plane tree (F1) is in good condition but slightly pushes the curb out	Tree to be removed due to construction
17 Lafayette Avenue	40" Red Oak (F1) is in good condition and overhangs part of the curb and road	Tree to be removed due to construction
19 Lafayette Avenue	24" tree with roots overhanging the curb and pushing the curb out	Tree to be removed due to construction