

LOCATION	OBSERVATIONS	RECOMMENDATIONS
250 Wayne Avenue	48" tree with roots overhanging the curb and pushing the curb out	Tree to be removed due to construction
248 Wayne Avenue	36" Pin Oak (F1) is in good condition with roots overhanging the curb and road	Tree to be removed due to construction
224 Wayne Avenue	18" Red Oak (F1) is in poor condition	Tree to be removed due to poor condition
204 Wayne Avenue	60" Willow Oak (F1) is in good condition with roots overhanging the curb and road	Tree to be removed due to construction
415 Wood Lane	22" Pin Oak (F2) is in poor condition with roots overhanging on the curb	Tree to be removed due to poor condition and construction
415 Wood Lane	22" Red Oak (F3) is girdling itself and is in poor condition	Tree to be removed due to poor condition
421 Wood Lane	16" Sugar Maple (S1) might interfere with construction if storm drain needs to be replaced	Tree to be removed due to construction
221 Wayne Avenue	16" Red Maple (F1) is in good condition slightly pushing the curb out	Tree to be removed due to construction
241 Wayne Avenue	36" London Plane (F1) is in good condition with roots overhanging the curb	Tree to be removed due to construction
251 Wayne Avenue	52" Pin Oak (F1) might interfere with construction if storm drain needs to be replaced	Tree to be removed due to construction