

Gfld. File #	Applicant	Location	Work allowed under Emergency Cert.	Site Visit	Determination Issued
02--08	Town of Greenfield	Millbrook Well Site			
02--09	Town of Greenfield	Country Club Road			
02--11	DPW EMERG CERT	63/73 Orchard Street 25 Spring Terrace			
02--14	DPW EMERG CERT	Spring Terrace			
02--15	DPW EMERG CERT	Guitford Rail System			
02--17	Mass Highway	I91 Slope Repair			
03--05	Mowry and Schmidt Inc	WMECO Power Cou			
03--07	DPW EMERG CERT	Spring Terrace			
03--16	DPW EMERG CERT	Spring Terrace			
03--17	Regis Johnston MacNeil	108 Cresent St			
03--18	Charles Koch	75 Wayland Drive			
04--01	Jerry Bricker	8 River Rd			
04--04	Renaissance Excavating	52 Country Club Road			
04--13	Charles Koch	75 Wayland Drive			
04--16	Krystyna Colburn	108 Cresent Street			
04--19	Rudolph Szolbort	85 Phyllis Lane			
04--20	DPW EMERG CERT	Spring Terrace			
04--24	Charles Koch	75 Wayland Drive			
05--09	College Park	25 Keegan			
05--14	DPW EMERG CERT	Bascomb School Road			

05--25	Davenport Trucking	30 Colrain			
05--27	Douglas stotz	54 factory hollow road			
05--28	Berkshire Gas Company	Meade St			
05--31	George Manietty	187 Plain			NOT ISSUED
05--33	DPW EMERG CERT	Meridian Street Dam			12/19/2005
06--02	Maple Brook	Sewer Line,			2/3/2006
06--03	DPW EMERG CERT	Property adjacent to 49 Gold Street,			2/3/2006
06--07	DPW EMERG CERT	Shelburne Road, across from 70 shelburne EMERG CERT			
06--09	DPW EMERG CERT	green river swim area			
06--23	Tigh&Bond	Wheeler Brook Green River			
07--07	DPW EMERG CERT	beaver dam			4/3/2007
07--21	DPW EMERG CERT	remove collapsed building			
08--07	DPW EMERG CERT	Mohawk Trail: Water Main			4/18/2008
09--04	DPW EMERG CERT	Pumping station		12/10/2008	1/27/2009
09--13	DPW EMERG CERT	off Country club road: cherry rum brook		4/15/2009	5/4/2009
09--16	DPW EMERG CERT	Bernardston Road/Rt 2 W: water main		6/10/2009	6/10/2009
09--21	DPW EMERG CERT	Cherry Rum Brook behing Silvercrest	Breach beaver dam	8/25/2009	8/25/2009
09--28	DPW EMERG CERT	Cherry Rum Brook	Breach beaver dam	2/2/2010	2/5/2010
11--04	DPW	Cherry Rum Brook - Beaver Dam		6/21/2011	
11--07	Glen Brook	683 Leyden		8/8/2011	8/15/2011
11--12	DPW EMERG CERT	Covered Bridge			9/19/2011
11--13	DPW EMERG NOTF	Eunice Williams Drive - Green River Pumping Station			9/23/2011

11--14	DPW EMERG NOTF	Green River Dam			9/26/2011
11--16	DPW EMERG CERT	Rt 2A Bridge Sewer Repair		10/24/2011	10/26/2011
11--17	DPW EMERG CERT	2 Mead Street, Riverbank restoration		10/25/2011	10/26/2011
13-06	DPW	Cherry Rum Brook - Beaver Dam		5/2/2013	
13-11	Joe Sabella	562 Leyden Road - collapsed culvert		7/23/2013	7/24/2013
14-10	Meadowview Manor Condo Association	Meadowview Condo		7/24/2014	7/28/2014
14-12	DPW	sewer Right-of-Way off of Elm Street		8/8/2014	8/11/2014
15-03	DPW	Shelburne Road west of Rt 2 overpass	Re-armor bank with rip rap where washout has undermined roadway	3/30/2015	3/30/2015
15-05	College Park Trust	72 Colrain Road	Breach beaver dam	7/10/2015	7/14/2015
16-03	Northrop Grumman	11-17 Meridian Street	Extend cofferdam ~ 25ft north in order to excavat the newly found contamination	1/22/2016	1/26/2016
16-04	Greenfield DPW	Allen Brook Culvert - Plain Road	Repair road + portion of culvert headwall	2/25/2016	2/26/2016
17-01	Greenfield DPW	Punch Brook at Plum Tree Lane	Breach beaver dam + trap beaver	12/20/2017	12/20/2017
18-01	National Grid	Transmission Lines in Green River (Access by 91 Glenbrook Drive)	Repaire and stabilize transmission line poles (Y177 & E205E)	1/22/2018	1/23/2018
19-01	Greenfield DPW	Adjacent to 72 Silvercrest Lane & 56 Country Club Road	Breach 2 beaver dams	2/7/2019	2/7/2019
19-02	Greenfield DPW	Adjacent to 72 Silvercrest Lane	Breach 1 beaver dam	6/20/2019	6/20/2019
19-03	Greenfield DPW	562 Leyden Road	Breach 1 beaver dam	9/?/2019	9/10/2019
19-04	Greenfield DPW	Cherry Rum Brook adjacent to Cherry Rum Plaza	Breach 1 beaver dam	9/?/2019	9/10/2019
19-05	Greenfield DPW	Cherry Rum Brook adjacent to Cherry Rum Plaza	Breach 1 beaver dam	11/5/2019	11/26/2019
19-06	Greenfield DPW	Cherry Rum Brook adjacent to Cherry Rum Plaza	Breach 3 beaver dam	11/5/2019	12/13/2019
20-01	Greenfield DPW	338 Deerfield Street	Remove tree from the Green River	1/24/2020	1/28/2020
22-01	Hasso Ewing	1 Birch Street	2 trees & hanging branch removal	6/22/2022	6/27/2022
22-02	DPW	Cherry Rum Brook adjacent to the Cherry Rum Plaza	Beaver dam	10/17/2023	10/18/2023
22-03	DPW	Across from 469 Barton Road	Guard rail repair	12/12/2023	12/21/2023
23-01	New England Power Company	Off Health Camp Road	Stabalize structure		3/8/2023
23-02	Fairview Landscapes	739 Bernardston Road	Tree cutting	3/10/2023	3/14/2023
23-03	DPW	Riverside Drive	coir logs, root wads, gravel, riprap	5/1/2023	5/15/2023
23-04	DPW	7 Newell Pond Place	install pipes, backfill w/ gravel	7/24/2023	7/25/2023
23-05	Conley's	64 Scout Road	Repair driveway/culvert	7/24/2023	7/28/2023

23-06	DOT	Route 2 over Fall Brook	restabilize bank	7/24/2023	7/26/2023
23-07	DOT	47 Cheapside Street	Culvert repair	11/1/2023	11/1/2023
24-01	DPW	Eunice Williams Drive	Remove material from culvert	1/10/2024	1/12/2024