| CERTIFICATE OF LOCATION OF GOVERNMENT CORNER | | |
|--|---------------------|--|
| WEST QUARTER Corner of Section 19 , Township 39 , Ronge 23 , 4TH P.M. STATE OF MINNESOTA, County of KANABEC | | |
| At the corner location shown on the sketch: On 05/29/2003 Found a 7/8 inch capped Rebar. | | Kanabec County U.S. Survey Feet Coardinates NAD 1983, HARN 1996 Adjustment Obtained by RTK GPS Observation Northing= 145292.228 Easting= 406686.123 Note: NAD 1983, HARN 1996 Adjustment coardinates are NOT compatible with NAD 1983 coardinates Note: 1 Meter=3937/1200 U.S. Survey Feet |
| SKETCH OF REFERENCE TIES | | |
| COUNTY STATE AID HIGHWAY NO. 11 P. | | TIES ARE TO A SPIKE IN THE NEAR FACE 10.24 108.26 TIES ARE TO A SPIKE IN THE NORTH FACE 108.26 TIES ARE TO A SPIKE IN THE NEAR FACE 24" OAK TIES ARE TO A SPIKE IN THE NEAR FACE 24" OAK |
| Statement of evidence relative to this corner location is on back of page. | | |
| I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. The Decreption of the data of th | County of the Count | certify that this document was filed in ty Recorder's office atM. on the day ofA.D., 20ecorder_ |
| Land Surveyar, [] Professional Engineer | BY | Deputy |
| [] County Surveyor, [] County Engineer | | NT NO. |

STATEMENT OF EVIDENCE

FROM TIE SHEET NO. 476-A.

Most reference ties were intact.

The roadway regraded in 1996. We located the section corner prior to construction and placed additional reference outside of the new construction limits.

Before the roadway was paved in 1997, the corner was re-established according to reference obtained previously. Additional references were also placed.

May 2003

Found monument, verified field ties and established Kanabec County coordinates on monument.