
CITY OF SHREWSBURY

Municipal Wards



SPORT COURT ASSESSMENT MATRIX


Courts and Conditions

Type and Location

1. Wehner Park







3. Ackfeld Park Two Tennis Courts One Sand Volleyball Court



4. Hartry Park Half Basketball Court





SCAN THIS CODE FOR ONLINE SURVEY OR GO TO

WWW.SURVEYMONKEY.COM/R/SHREWSCT01

CRITERIA OVERVIEW

Court Type & Location

- . Year Installed

- . Ward
- Surface

Scoring for the Comfort and Convenience elements listed below is:

Comfort and Convenience

- 1 element is present at or in close proximity
- o element is not present or along a paved route
- . Site Furnishings
- Shaded Play Area
- . Restrooms

TOTAL SCORE

- . Picnic Shelter
- Drinking Fountain
- Lighting (Security)

Courts and Conditions

Age: Age scoring is:

- 3 five years old or less
- 2 six to fourteen years old
- o fifteen years or older

General Condition:

Scoring for the general condition of the sport court is:

- 3 all components (surface, striping, hoops/nets, etc.) are in good condition and clean.
- 2 overall good condition, but surface or fixtures may be faded or peeling
- o significant issues with surface, equipment is cracked, broken, or removed.

Paved Accessible Walk:

The sport court scoring for paved accessible walks is: 3 - accessible paved walk five feet wide or greater

- 2 paved walk in need of repair, less than five feet wide, or not per ADA requirements
- o no paved walk to sport court

Surfacing:

Sport court surfacing scoring is:

- 3 ideal surfacing for specific sport in good condition
- 2 adequate surfacing in fair condition for use
- o surfacing in poor condition

Lighting:

Lighting scoring is:

- 3 lighting provided
- 2 some lighting, older fixtures, etc.
- o no lighting provided











CITY OF SHREWSBURY, MO.

Comfort & Convenience



| | CRITERIA | SCORE | NOTES | |
|---------------------------|---------------------|-------|---|--|
| 2 % | Ward | NA | Two, along the border of wards one and three | |
| Court & Location | Surface | NA | Synthetic turf on asphalt base | |
| | Year Installed | NA | Unknown, > 25 years | |
| Equipment & Accessibility | Age | 0 | Court installed over 25 years ago | |
| | General Condition | 2 | Fair condition overall, nets in good condition, turf seams separating | |
| | Paved Walk | 3 | Accessible path from parking to courts | |
| | Surfacing | 0 | Turf is nearing end of lifespan, hard surface preferred | |
| | Lighting | 0 | No court lighting provided | |
| | Site Furnishings | 0 | No benches near court | |
| | Play Area | 1 | Playground with some shade located adjacent to courts | |
| ort & nience | Restrooms | 1 | Restroom nearby | |
| Con | Picnic Shelter | 1 | Large shelter nearby, easy access | |
| | Drinking Fountain | 1 | Drinking fountain located along path to court | |
| | Lighting (Security) | 0 | No lighting along path | |
| | TOTAL SCORE | 9 | | |







PLACE POST-IT NOTES HERE







| | CRITERIA | SCORE | NOTES |
|----------------------------------|---------------------|-------|--|
| ج لاء | Ward | NA | One |
| Court & Location | Surface | NA | Asphalt |
| ပ္ပိ | Year Installed | NA | Unknown, > 25 years |
| • | Age | 0 | Surface installed over 25 years ago |
| nt & | General Condition | 0 | surface cracking /slope, court undersized |
| E quipment Accessibili | Paved Walk | 2 | Path provided, not ADA compliant |
| quip | Surfacing | 0 | Sloped surface, cracks |
| й« | Lighting | 2 | Lighting provided |
| | Site Furnishings | 0 | No benches next to court for players or spectators |
| e c | Play Area | 1 | Playgrounds with some shade located near courts |
| fort & enience | Restrooms | 1 | Restroom nearby |
| omfa 1ver | Picnic Shelter | 1 | Shelter nearby |
| Conve | Drinking Fountain | 1 | Drinking fountain near shelter |
| | Lighting (Security) | 1 | Lighting provided along paths |
| | TOTAL SCORE | 9 | |

Basketball

| | CRITERIA | SCORE | NOTES |
|---------------------------|---------------------|-------|--|
| 2 % | Ward | NA | One |
| Court & Location | Surface | NA | Asphalt |
| ပို့ | Year Installed | NA | Unknown, > 25 years |
| | Age | 0 | Court installed over 25 years ago |
| nt 8 | General Condition | 0 | Hoop in good condition, surface cracking, sloping |
| ome sssib | Paved Walk | 2 | Path provided, not ADA compliant |
| Equipment Accessibilit | Surfacing | 0 | Sloped surface, cracks |
| Ш | Lighting | 2 | Lighting provided |
| | Site Furnishings | 0 | No benches next to court for players or spectators |
| 0 K2 | Play Area | 1 | Playgrounds with some shade located near courts |
| nfort & renience | Restrooms | 1 | Restroom nearby |
| omf | Picnic Shelter | 1 | Shelter nearby |
| Conv | Drinking Fountain | 1 | Drinking fountain near shelter |
| | Lighting (Security) | 1 | Lighting provided along paths |
| | TOTAL SCORE | 9 | |











PLACE POST-IT NOTES HERE















| | CRITERIA | SCORE | NOTES |
|---------------------------|---------------------|-------|---|
| એ <u>દ</u> | Ward | NA | Two |
| Court & Location | Surface | NA | Synthetic turf on asphalt base |
| ပို့ | Year Installed | NA | Unknown, > 25 years |
| . N | Age | 0 | Court installed over 25 years ago |
| nt & | General Condition | 0 | turf seams separating, fence bowing |
| Equipment Accessibilit | Paved Walk | 2 | Path provided from parking to courts |
| quip | Surfacing | 0 | Turf is nearing end of lifespan |
| ш~ | Lighting | 2 | Court lighting provided |
| | Site Furnishings | 1 | Bench located along path |
| ט ג | Play Area | 0 | No playground located nearby |
| ort & | Restrooms | 0 | Portable restroom along path |
| Convenier Convenier | Picnic Shelter | 0 | No shelter provided |
| Ŭ Ö | Drinking Fountain | 1 | Drinking fountain located along path to court |
| | Lighting (Security) | 1 | Lighting provided, located next to police station |
| | TOTAL SCORE | 7 | |

Sand Volleyball

| | CRITERIA | SCORE | NOTES |
|---------------------------------|---------------------|-------|-----------------------------------|
| 2 K2 | Ward | NA | Two |
| Court & Location | Surface | NA | Course Sand |
| ပိုင် | Year Installed | NA | Unknown, > 25 years |
| | Age | 0 | Court installed over 25 years ago |
| nt 8 | General Condition | 2 | Court overgrown in locations |
| Equipment Accessibili | Paved Walk | 0 | No paved access |
| quip | Surfacing | 2 | Course sand |
| ш ~ | Lighting | 0 | No lighting |
| | Site Furnishings | 1 | Picnic table and trash |
| o V | Play Area | 0 | No playground located nearby |
| nfort & enience | Restrooms | 0 | No restroom nearby |
| Conver | Picnic Shelter | 0 | No shelter provided |
| ŭō | Drinking Fountain | 0 | No drinking fountain |
| | Lighting (Security) | 0 | No lighting |
| | TOTAL SCORE | 5 | |










| | CRITERIA | SCORE | NOTES | |
|---------------------------|---------------------|-------|--|--|
| Court & Location | Ward | NA | One | |
| | Surface | NA | Concrete | |
| | Year Installed | NA | 2021 | |
| Equipment & Accessibility | Age | 3 | Surface installed less than 5 years ago | |
| | General Condition | 3 | Hoop in good condition, surface flat and in good shape | |
| | Paved Walk | 3 | Accessible Path provided from parking to courts | |
| | Surfacing | 3 | Ideal surface for use | |
| | Lighting | 3 | Lighting provided | |
| | Site Furnishings | 1 | Beach provided | |
| nce | Play Area | 1 | Playgound with some shade located near courts | |
| Comfort 8 | Restrooms | 0 | Portable restroom in park | |
| | Picnic Shelter | 1 | Shelter close to court | |
| | Drinking Fountain | 1 | Drinking fountain located close to court | |
| | Lighting (Security) | 1 | Lighting provided along paths | |
| | TOTAL SCORE | 20 | | |







PLACE POST-IT NOTES HERE



