Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occuring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Casey middle								
Location	Room 114 Sink	Room 129 Sink	Room 132 Sink # 2	Room 132 Sink # 5	Stage Sink	Room 139 Sink # 1	culty Bathroom Sink # 1	Mezzaninne Sink
Test results	22.2	20.5	15.6	17.8	96.8	21.3	37.8	65.6
Test results								
Remediation								
Back in use								
Location								
Test results								
Remediation								
Results								
Back in use								
Location								
Test results								
Remediation								
Back in use								
Location								
Test results								
Remediation								
Back in use								