Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occuring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Forest								
Location	38 Bathroom Sink # 1	36 Classroom Sink	20 Classroom Sink # 3	19 Classroom Sink	12 Classroom Sink	9 Bathroom Sink	1 Classroom Sink	Library Offcie Sink
Test results	98.10	16.80	20.50	15.10	21.60	15.60	138.00	140.00
Remediation								
Results								
Results								
Results								
Back in use								
Location								
Test results								
Remediation								
Results								
Back in use								