Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occuring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Maple West								
Location	109 Classroom Sink # 1	Library Office Sink	102 Classroom Sink	Boiler Room Eyewash	Boiler Room Sample	102 Classroom Sink # 2	101 Classroom Sink # 2	Kitchen Pot Filler
Test results	15.40	18.10	16.20	200.00	15.80	22.40	76.00	28.30
Remediation								
Results								
Test results								
Back in use								
Location								
Test results								
Remediation								
Results								
Results								
Back in use								