

Williamsville CSD

Locations of Water Test Samples Greater than 15 ppb

NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.

Dodge								
Location	105 Bathroom Sink	144 Bathroom Sink	Basement Source	Basement Sink				
Results	18.10	18.50	42.70	43.50				
Remediation	Flushing	Flushing	Flushing	Flushing				
Results	19.80	27.40	12.30	3.25				
Back in use			9/29/2021	9/29/2021				
Location								
Results								
Remediation								
Results								
Back in use								