

**Williamsville CSD**

**Locations of Water Test Samples Greater than 15 ppb**

**NOTE: Fixture replacement is being prioritized by our facility staff and is occurring in an expedited manner. New water samples are sent to the testing lab with an accelerated turn-around time.**

<b>East high</b>								
Location	Pool Room Eye Wash	Kitchen Sink # 5	Kitchen Sink # 8	Room 102 Sink #1	Room 103 Sink # 4	Kiln Room Sink	Room 117 Sink # 4	Room 117 Sink # 6
Test results	2080	20.2	27.5	18.6	20.4	30.4	52.6	97.2
Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing
Test results	133	3.68	3.9	3.76	3.52	3.03	2.52	4.21
Back in svc.		9/29/2021	9/29/2021	9/29/2021	9/29/2021	9/29/2021	9/29/2021	9/29/2021
Location	Room 117 Sink #7	Room 117 Sink # 8	Room 119 Sink # 1	Room 119 Sink # 2	Room 119 Sink # 3	Room 119 Sink # 4	Room 119 Sink # 5	Room 113 Sink
Test results	101	44.9	32.6	23	71.2	50.4	15.4	38.3
Remediation	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing	Flushing
Test results	6.99	ND	8.07	1.99	3.19	3.79	2.29	2.26
Back in svc.	9/29/2021	9/29/2021	9/29/2021	9/29/2021	9/29/2021	9/29/2021	9/29/2021	9/29/2021
Location	Mens Lav by Aud Sink	Health Office Sink # 1	Coaches Office Lav Sink	Boys Red locker Room Sink	Kiln Room Sink # 2			
Test results	29.2	21.8	21.2	19.2	30.4			
Remediation	Flushing	Flushing	Flushing	Flushing	Flushing			
Test results	88	14.6	236	20.3	2.77			
Back in svc.		9/29/2021			9/29/2021			
Location								
Test results								
Remediation								
Back in svc.								
Location								
Test results								
Remediation								
Test results								
Back in svc.								
Location								
Test results								
Test results								
Test results								
Remediation								
Back in svc.								